

MAY 0 5 1997

STATE OF INCHIGAN

COMMISSION

Surveyor's Michigan License No. 🗻

LAND CORNER RECORDATION CERTIFICATE 96 DEC 31 PM 2: 24

EMHET RECO	COU	YTY	AR (
605001	D14	_	

		Filing Requiren	nent of Act 74, Mich.	P.A. 1970	de s	
For	corners in			X.	Denna G. Sijee	,
	EMMET	Located In:	Corner Code ##		PEGISTER OF PETOS	
1.	Public Land Survey E.C.R.P#	120 T R	I-6		PAGE 141	
2. 3.	Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R		Registe	r of Deeds Stamp & F	ile Number
Á	Lot No.	Recorded Plat		~	**	
4. 5.		recorded Flat			A B C D E F G	HIJKI
in li cur Mar abo Cou exp	nereby certify that under receives 1 and 2 above were interest manual of survey instructions of the conformance with the conformance wi	, in a field survey on December of P.A. 74, Michigan P.A. of a conformance with regulations and uctions of the United States Departmacount of Law and/or that the corner put the rules of the Michigan Board of the established, monumented, re-monormers, all in the same town and	1970, the corner points mentioned the Interior, Bureau cooints mentioned in lines 3, and Surveyors or by a Decinumented, recovered, for range, may be recorded or subsequent restorations.	ntioned 6 I in the 7 I and 5 8 ree of a 9 Ind as 10 I and 11 I 2 I 3	-18 -17 -16 -1 -19 -20 -21 -2 -30 -29 -28 -2	3 — 2 — 11 — 5 — 14 — 23 — 14 — 35 —
	·	AGE FOR HISTORY)				
₿.	I-5, Found I" Iron Bar in Mo	ovidence found and/or method ap conument and replaced with a 2" dia amet County Remonumentation Ca	meter, 30" long PVC Pipe			
	THIS CORNER IS ACCEPTED BY THE EMMET COUNTY REMONUMENTATION GROUD AS A FAITHFUL AND CAREFUL PERPETUATION OF THE ORIGINAL CORNER.			P.A. 345 OF 1990 Emmiet County R.E. Out		
					12-30-96	
C.	Placed a 2" diameter, 30' Remonumentation Cap a corner position. (5) S34°W 48.26' - 8" (6) N68°E 50.60' - Pow (8) N42°W 109.44' - S6 (11) S52°W 48.51' - 4"	ont for corner and accessories estaining PVC Pipe with a Base magnitude in Iron Bar in Monument Both Cedar (found spike nail with 10710 for Pole (found spike nail with 1540 outheast Corner Garage Foundation Balsam Fir (found spike nail with 2746).	et and a standard Brass En x. Further reset monume cap on face of tree) 11 cap) 1. 27463 cap)	nmet County		•

LIBER A
PAGE 142

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 120 T34N R6W - 1-6

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

Date	Surveyor	Found (Witnesses)	
1840	- GLO	Set Post	(1)	Cherry 4 N55E 12
			(2)	Balsam 7 S70W
1887	Keep	Set Post	(3)	S71°30'W 36' - 14" Sugar
			(4)	N15°E 35' - 12" Cedar
1901	Williams	1/4 Post	(9)	S40°W 60-1/2 links - 16" Maple
			(10)	S08°E 82 links - 12" Birch
1973	J.H. Green	Found 3/4" Pipe	(5)	S38°W 48.25' - 6" Cedar
		(Liber 249, Page 509)	(6)	N68°E 50.08' - Power Pole
1974	G.E. Young	Found 1" Pipe	(5)	S31°W 48.30' - 6" Cedar
		(Liber 1, Page 182, LCR		N58°E 50.14' - Power Pole
1990	M.A. Trowbridge	Found I" Iron Bar	(5)	S35°W 48.20' - 8" Cedar
		in Monument Box	(6)	N63°E 50.62' - Power Pole
		(Liber 2, Page 310, LCR)		N03°E 20.18' - Fence Corner
			(8)	N42°W 109.44' - Southeast Corner
	•		` ,	Garage Foundation