MAR 0 4 1998

STATE OF MICHIGAN EMMET COUNTY RECORDED

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 DEC 30 PM 4: 15

For corners in		,	110
EMMET (County)	Located In: LITTLE TRAVERSE	Corner Code # TOWNSHIP	REGISTER OF DEFOS
1. Public Land Survey	T <u>35N</u> R <u>5W</u> TR	<u>l-10</u>	

LIBER A PAGE 235

Register of Deeds Stamp & File Number

ł. Lot No ,  Recorded Plat	
5. Private Claims	

I, Richard E. Oelke , in a field survey on 19 December , 19 9 7 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent resstoration:

I-10.... 1/4 Corner bet., secs. 26,&27, T35N, R5W

See Outline of Corner History on back.

171

GLO in 1840, set post... MDOT found 1" pipe in 1928 and has been used by local surveyors till present... However in 1974 Bidstrup set and recorded a LCRC for a concrete monument, which he set approximately 2.6' E'ly of found 1" iron pipe mentioned above... This corner has also been used by several local land surveyors... After reviewing Bidstrup's field notes it was concluded that the concrete monument was incorrectly set.

APPROVED LAND CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-10.... 1/4 Corner bet., secs. 26,&27, T35N, R5W

Found 1" iron pipe, firmly set in very wet soil....

WITNESSED AS FOLLOWS:

N77°E 2.57' concrete monument S87°E 4.17' 7" elm, with a nail in N face

\$16°W 29.76' 8" aspen, with a nail in E face \$53°W 46.62' 10" tamarack with a nail in N face

N58°W 24.32' 6" birch, with a nail in SE face

RICHARD E. OELKE PROFESSIONAL SURVEYOR No. 33983

P.A. 345 OF 1990

Emmet County

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

#### I-10.... 1/4 Corner bet.. secs. 26,&27, T35N, R5W

Over the 1" iron pipe, drove a 2" diameter, 30" long PVC pipe, with a standard brass Emmet County Survey Remonumentation Program cap. This position is accepted as a careful and faithful perpetuation of the original corner.

NEW WITNESSES AS FOLLOWS:

N43°E 63.65' 3" cedar, tagged PS# 33983 in S face

S73°E 37.41' 4" birch, tagged PS# 33983 in E face

Signed by	RE. CELVE	_Date _	19 December 1997
Surveyor's Michigan	License No. 33983		

#### EMMET COUNTY REMONUMENTATION PROGRAM

#### CHRONOLOGY OF GLO CORNER

REMON. CORNER #166 LCRC #35-05-I10 TOWNSHIP...BEAR CREEK

CORNER COMMON TO SECTIONS 26 & 27, T35N, R5W

DATE	SURVEYOR	FOUND/SET	WITNESSES	
1840	GLO	8" Hemlock	Comes on margin of lake. No witnesses.	
1928 At	MDOT  pove survey notes rec	1" Gas Pipe with shovel eived by M.Trowbridge, fro	handle in end (no witnesses noted). om MDOT (Ed Morse, Area Supervisor).	
1945	John Gehman Survey Map	1" Iron Post	No witnesses noted	
1956	? Survey Map for Francis B.Knig	Found 1" Pipe ht	No witnesses noted	
1957	T.F.Schweigert Survey Map for August Feike	Found 1/2" Iron Pipe	No witnesses noted	
195_	M.C.Feindt Survey Map for August Feike	Found 1" Gas Pipe	No witnesses noted	
1961	Schweigert & Young, Inc. Survey Map for Edith Haar	Found 1/2" Iron Pipe	No witnesses noted	
?	G.Young? Survey Map for Art Bellmer	1/2" Pipe	No witnesses noted	
1962	Schweigert & Young Survey Map for State Homes, I	Found 1/2" Iron Pipe nc.	No witnesses noted	
1962	H.E.Irish Survey Map for AI Farnstrom	?	?	
? Co.	G.A.Fauser nsumers Power Co. S	Found Corner arvey sketch of Section 26	No witnesses noted, T35N, R5W	•
?	MDOT Survey Map Proj. M 024 20	Found 1" Gas Pipe with Shovel Handle in end.	No witnesses noted	
1969	Schweigert & Young Inc.	Plat of George Anna Est but no corner material o	tates. Corner is called for on Plat, r witnesses are specified.	
1972	G.E.Young Survey Map for Lister	Corner is called for on a material or witnesses are		

	MAR 0 4 199	8	Marian Company		m.é
	SECTION	RICHA OEL PROFESS SURVE No 3399	KE SIONAL EYOR	ľΒ	ER A
1974	R.E.Bidstrup	Concrete Monumerer	e 10 Messau	06.00	***
	Survey Map L.253, Pg.274	(Map shows 1" I.P. Fd. 0.59 South & 2.56'	2) S06°W	26.78' 45.52'	W. Birch Clump "X" in Nly R.R. Track
		West of monument)	3) S48°E	45.62'	"X" in Nly R.R. Track
1975	J.H.Green Survey Map	Corner is called for on r material or witnesses are	nap, but no corn	er	
1975	R.E.Bidstrup	Set	1) N53°W	26.78'	W. Birch Clump
	Survey Map L.261, Pg.417	Concrete Monument (Map shows 1" I.P.	2) S06°W	45.52'	"X" in Nly R.R. Track
		Fd. 0.59' South & 2.56' West of set monument)	3) S48°E	45.62'	"X" in Nly R.R. Track
1977	J.H.Green Survey Map	Corner is called for on material or witnesses are	nap, but no corne specified.	er	
1978	R.E.Bidstrup	Found	1) N53°W	26.78	W Birch Clumn
	Survey Map L.283; Pg.208	Concrete Monument	2) S06 W	45.52°	W. Birch Clump "X" in Nly R.R.
		(No reference to 1" I.P. on this map)	3) S48°E	45.62'	Track "X" in Nly R.R. Track
1978	J.H.Green	Found 1-1/4" Pipe &	4) S21'W	29.65'	5" Donlor
	Survey Map	placed T-Iron inside	5) N51°W	25.03°	5" Poplar 6" Birch
			6) S55°W	46.64*	5" Tamarac
1980	J.H.Green	Found 1-1/4" Pipe	4) S21'W	29.65'	5" Poplar
	Survey Map	with T-Iron inside	5) N51°W 6) S55°W	25.02' 46.64'	6" Birch 5" Tamarac
1980	J.H.Green	Found 1 1/4" Ding &	•		
	LCRC	Found 1-1/4" Pipe & placed T-Iron inside	4) S21°W 5) N51°W	29.65' 25.02'	5" Poplar 6" Birch
	L.2, Pg.34	•	6) S55'W	46.64	5" Tamarac
1980	J.H.Green	Found 1-1/4" Pipe	4) S21 W	29.65'	5" Poplar
	Survey Map L.316, Pg.284	with T-Iron inside	5) N51'W	25.02'	6" Birch
	L.310, Fg.204		6) S55°W	46.64'	5 <sup>s</sup> Tamarae
1982	M.A.Trowbridge	Found	1) N53'W	26.78	W. Birch Clump
•	Survey Map L.326, Pg.914-	Concrete Monument	2) S06°W	45.52'	"X" in Nly R.R. Track
			3) S48'E	45.62*	"X" in Nly R.R. Track
1984	J.H.Green	Found 1-1/4" Pipe	4) S21°W	20 <i>651</i>	St Danie
	Survey Map	with T-Iron inside	5) N51 W	29.65' 25.02'	5" Poplar 6" Birch
			6) S55*W	46.64	5" Tamarac
1986	M.A.Trowbridge	Found	7) S52°E	1.83'	5" Elm
	Survey Map L.371, Pg.630	Concrete Monument	8) N87°W 9) N55°W	2.60° 26.25°	T-Iron 5" Birch
1986	M A Thomas 11	East Division 1	AL AL WA		
1300	M.A.Trowbridge LCRC	Found T-Iron and Concrete Monument	7) S52°E 8) N87°W	1.83' 2.60'	5" Elm T-Iron
	L.2, Pg.160	(used Con. Mon.)	9) N55°W	26.25	5" Birch
1007	3.5.4.77				
1986	M.A.Trowbridge Survey Map	Found Concrete Monument	7) S52°E 8) N87°W	1.83° 2.60°	5" Elm T-Iron
	· · · · · / · · · · · · · · · · · · · ·	ALL MAINVILL	0) 1101 11	<i>2</i> .₩	T-MOH

### ESSI 70 NAM

Maria de la compansión de

(.\_.

## REMONUMENTATION SUPPLY SUPPLY

	L.381, Pg.975		9) N55°W	26.25	5" Birch	
1987	J.H.Green	Found	4) S21°W	20 657	511 To 1	
	Survey Map	T-Ir w/in Pipe		29.65	5" Poplar	
	Durioj Map	1-11 W/M Tipe	5) N51°W	25.02'	6" Birch	
			6) \$55°W	46.64'	5" Tamarac	
1987	M.A.Trowbridge	Found	7) S52°E	1.83'	5" Elm	
	Survey Map	Concrete Monument	8) N87'W	2.60'	T-Iron	
			9) N55°W	26.25'	5" Birch	
1988	J.H.Green	Found	1) N53*W	26.78'	W. Birch Clump	
	Survey Map	Concrete Monument	2) S06°W	45.52'	Cross in Nly	
	•	•	3) S48°E	45.62*	R.R. Track	
			<i>5)</i> 546 E	45.02	Cross in Nly R.R. Track	
1989	J.H.Green	Found 1-1/4" Pipe	4) S21°W	29.65'	· 5!! Daulan	
	Survey Map	placed T-Iron inside			5" Poplar	
	y map	paced 1-1101 hiside	5) N51 W	25.02'	6" Birch	
			6) S55°W	46.64'	5" Tamarac	
1990	M.A.Trowbridge	Found	1) N53°W	26.78'	W. Birch Clump	
	Survey Map	Concrete Monument	2) S06'W	45.52'	"X" in Nly R.R.	
					Track	
			3) S48 <b>°</b> E	45.62'	"X" in Nly R.R. Track	
	i .		8) 1" Pine 2.5	6W and 0	11ack	
			8) 1" Pipe 2.56 W. and 0.66 S. of West 1/4 Cor.			
1991	M.A.Trowbridge	Found	7) S52 <b>°</b> E	1.83'	5" Elm	
	Survey Map	Concrete Monument	8) N87°W	2.60'	T-Iron	
	L.441, Pg.770		9) N55°W	26.25'	5" Birch	
	•		2) S06°W	45.52'		
		,	2) 500 11	43.36	"X" in Nly R.R. Track	
		·	3) S48°E	45.62*	"X" in Nly R.R.	
•			•	-	Track	
			·			
1992	M.A.Trowbridge	Found	7) S52*E	1.83'	5" Elm	
	Survey Map	Concrete Monument	8) N87'W	2.60'		
	L.472, Pg.958	Concrete Monument	0) N55*337		T-Iron	
			9) N55*W	26.25'	5" Birch	
•			2) S06°W	45.52'	"X" in Nly R.R. Track	
			3) S48°E	45.62'	"X" in Nly R.R.	
					Track	
1992	T.D.Swenor	Found	refer to P.A. 74, 1970 corner records,			
	Survey Map	Concrete Monument	being L.2, P.34	and I 2 D	ner records,	
	for Marge Kritcher	Co. Recs.	oeing 12, 154	and L.Z, F	.100 Emmet	
1992	T.D.Swenor	Referenced on Map			-	
	Survey Map	L. 2, P. 160			·	
	L.485, Pg.878	P.A. 74, 1970				
1993	T.D.Swenor	Corner is called for on m	an hut no come			
-	Survey Map for Kuntz & Rose	material or witnesses are	specified.			
1993	T.D.Swenor	Found	1) N53°W	26.78'	W. Birch Clump	
	Survey Map	Concrete Monument	2) S06*W	45.52'	Cross in Nly	
	for Anthony &		•		R.R. Track	
	Barbara Zambrowsk	d ·	3) S48°E	45.62'	Cross in Nly	
			•		R.R. Track	
					**	

# SURVEY & REMONUMENTATION

का सर्वी!श्रहेन्द्र

MAR 0 4 1998

LIBER A

PAGE2

## SECTION

1994	T.D.Swenor Survey Map for Gary Phillips	Found Concrete Monument	7) \$52°E 8) N87°W 9) N55°W 2) \$06°W	1.83' 2.60' 26.25' 45.52' 45.62'	5" Elm T-Iron 5" Birch "X" in Nly R.R. Track "X" in Nly R.R. Track
1995	T.D.Swenor Survey Map for Thompson	Found Concrete Monument	as rec in L.2,	P.160, Em	m Co. Records.
1996	M.A.Trowbridge Survey Map	Found Concrete Monument	1) N53°W 2) S06°W 3) S48°E	26.78° 45.52° 45.62°	W. Birch Clump "X" in Nly R.R. Track "X" in Nly R.R. Track
1996	Oelke	Found and used 1" iron p	pipe		
1996	Farriër	Found and used 1" iron p	oipe		

