SURVEY & REMONUMENTATION

APR 27 1995

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN EMMET COUNTY
RECORDED

	•	ישי ושי
For	corners	in
		_

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

1994 JUN -2 PM 2:51

ĿN	IME i	Located In:	Corner Code ##	4	40.		11	pro.				
Ea 2. Pro in S	County) Dic Land Survey CRP #50 perty Controlling Section cellaneous	City of Harbo T 35N R 6W T R T R T R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R R R T R	or Springs J-5	, ** Registe	· · · · · · · · · · · · · · · · · · ·	STER LIBE PAGI	R	4 28		V um	ber	
Pro	perty in Sec.	S T R										
5. Priv	rate Claims seph B. O'Neill	, in a field survey onApri	il , 19 <mark>94</mark>	2 3 4 	A B	C D	E F	G	3 3 10	-2-	K L	M 1
in lines current i Manager above w Court o	1 and 2 above were manual of survey in ment or by a decree ere in conformance	e in conformance with regulations structions of the United States Dep of a Court of Law and/or that the cor with the rules of the Michigan Boan	A. of 1970, the corner points mention and rules therefore as required in to partment of the Interior, Bureau of Lamer points mentioned in lines 3, 4 and of Land Surveyors or by a Decree ce-monumented, recovered, found	the and 7 d5 B	—18— —19— —30—	20-29-	21	3—	22	—1 ¹ 4- —23- —26-		24-25-
NOTE:	Not more than 4 on this certifica	te.	and range, may be recorded	11 12 13	31	32	33	,	34	35		36
	=	al monument and accessories a r of Section 11, T35N, R6W	and/or subsequent restoration:		•	-		-	-			Person
	•	oost N80°E, 18lks, 9" beech; ev for Becker, field notes shows										

1981 Bidstrup Survey for Sayan, found 1-1/2" iron rod.

1967 to 1991 Numerous surveys tied to 1-1/2" iron bar.

1991 O'Neill LCRC (3/23), found 1-1/2" iron bar at surface. Also found a 2" long 1" diam. iron shaft with collar and wooden stake alongside, 2' below pavement, 0.86'S and 0.20' W of the 1-1/2" iron rod at the surface. Plastic markers, 30" long

were placed at both found corners.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - J-5, South 1/4 corner of Section 11, T35N, R6W, on Lake Street

Found both corners as described and recorded in 1991 by J. O'Neill. Witnesses fit well. Found no written history verifying the position of the southerly (0.86') corner found by O'Neill in 1991. Although this corner may possibly represent an earlier position of this corner, the northerly corner has been accepted by the Emmet County Remonumentation Program as the best and most consistent position for the corner as it harmonizes with all of the surveys of record in this area, both prior to and subsequent to 1991, and is in very close proximity to the second corner (less than 1 foot). The southerly monument and monument box were pulled in order to avoid further confusion of the area.

This corner is accepted by the Emmet County Remonumentation Peer Group as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: J-5, South 1/4 corner of section 11, T35N, R6W, on Lake Street

Found and pulled the southerly plastic marker set in 1991 by J. O'Neill

Left in place the northerly 30" long plastic marker (with magnet) set in 1991 by J. O'Neill, and stamped the top "Emmet County Remonumentation". in road centerline east and west.

S40°E 31.48', found tag # 30095, N face 3-20" Basswood S52°W 50.86', found tag # 30095, NW face 34" Maple N54°W 55.74', found tag # 30095, SW face 18" Maple N52°E 48.49', found tag # 30095, NE face 14" Spruce

APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County (p.

Date

OF MICH JOSEPH B. O'NEILL ROFESSIONAL SURVEYOR No. 30095

Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.

29