MAR 1 6 1994

1. Public Land Survey

Property Controlling

Property in Sec.

in Section Miscellaneous

LAND CORNER RECORDATION CERTIFICATE Act 74, Mich. P.A. 1970

STATE OF MICHIGAN EMMET COUNTY RECORDED

1994 FEB 14 AM 10: 14

| For corners in MSSION | Filing Requirement of A | | |
|-----------------------|-------------------------|-------|--|
| EMMET | Located In: | Corne | |
| (County) | City of Harbor Springs | | |

r Code ## M-5 T 35N R 6W T.

_ T _ _ T _ Glenna A. Sijae

LIBER PAGE

3

5

7

9

10

11

12

Register of Deeds Stamp & File Number

OF MICHIGIA

JOSEPH B.

O'NEILL

PROFESSIONAL

SURVEYOR

No. 30095

A 0 1 2 5 1 0

Á

___ , Recorded Plat _ Lot No. Private Claims.

December Joseph B. O'Neill 19 _ , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: M-5, corner common to sections 12 & 13, T35N, R6W, and sections 7 & 18, T35N, R5W

1840 GLO

Set Post -- 5" Beech N61.5°W 33 links, 5" Beech S52°W 21 links

Found, no description 1888 J. Keep

1948 H. Irish

Found 2" Iron Pipe - NE cor. porch N30°W 118.2', SW cor. house N40°E 100.3'

24"maple S40°E 76.6', NE cor. house S55°W 72.4'

1977 R. Bidstrup

L.C.R.C., Liber 1, Page 277, Found 1 1/2" pipe L.C.R.C., Liber 2, Page 263, Found boat spike

1989 J. O'Neill 1991 J. O'Neill

L.C.R.C., Liber 3, Page 23, Found 2" pipe under boat spike

1967-1993

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Same position was used by several local surveyors

M-5, corner common to sections 12 & 13, T35N, R6W, and sections 7 & 18, T35N, R5W

Found as described and recorded in 1991 by J. O'Neill. Witnesses fit well, and the history of the corner appears to be consistent with this position.

This corner is accepted by the Emmet County Remonumentation Peer Group as a careful and faithful perpetuation of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-5, corner common to sections 12 & 13, T35N, R6W, and sections 7 & 18, T35N, R5W

Found and replaced plastic marker set in 1991 by J. O'Neill with a 2" dia. 30" long PVC pipe with a base magnet and a standard brass Emmet County Remonumentation cap, set in road intersection.

S35°E 56.36', found tag # 30095, NE face Power Pole S58°W 36.37', found tag # 30095, SE face Power Pole

N46°W 47.70', found tag # 30095, SW face Power Pole

N18°E 69.82', found tag # 30095, W face Power Pole

| | | 1. | a | 07/10 | |
|----------|----|-------|-----|--------|--|
| Signed b | oy | fourt | 1). | 0//100 | |
| • | - | | | | |

_____ Date December 30, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No. 30095