Jar 2 9 1390

STATE OF MICHIGAN EMMET COUNTY RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

98 DEC 30 PM 12: 00

_ SECTION	Filing Requirer	ment of Act 74, Mich. P.A. 197	
For corners in EMMET (County)	_ Located in:	Corner Code #	Glenna A. Sipe
			REGISTER OF DEEDS
1. Public Land Survey	T <u>36N</u> R <u>5W</u> T R	M9	A. A.
ECRP #189	T R		Libert
	T R T R T R T R		PAGE 348 Register of Deeds Stamp & File Number
4. Lot No, Record			ABCDEFGHIJKL
I. Michael A. Trowbridge, in a do hereby certify that under requirementioned in lines 1 and 2 above required in the current manual of su Bureau of Land Management or be mentioned in lines 3, 4 and 5 above Professional Surveyors or by a Decre-monumented, recovered, found as NOTE: Not more that 4 corners on this certificate. A. Description of original monuments, CORNER COMMON TO	2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 - 18 - 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36		
SEE CHRONOLOGY ON BAC	APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County R.E. CELVE, P.S., E.C. PEp. 29 DEC. 1998		
B. Description of corner eviden	ce found and/or method a	applied in restoring or reestablishi	ng corner:
M9, CORNER COMMON TO	SECTIONS 24, & 25, T3	86N, R5W	
Did not find 1840 GLO post	or witnesses. Did not find	d Hartzler's stone of 1879 (dug 2	diameter by 3' deep hole).
Found 5/8" rerod in monume	nt box set in 1978 by Ric	chard Bidstrup at intersection of re	pads north, south, east and west.

Found witnesses

7) S66°E (Az.114°)

82.92

6" Poplar

8) S46°E (Az.134°)

68.97

6" Poplar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M9, CORNER COMMON TO SECTIONS 24, & 25, T36N, R5W

The 5/8" Rerod noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program cap, which was placed within a standard Emmet County monument box. This position is accepted as the best available evidence of the position of the original corner. OF MICHIG

ADDITIONAL NEW WITNESSES:

S63°E (Az.117°) S54°E (Az.126°) 83.01

10" Poplar (27463 cap & nail in North face, set above found witness 7)

S46°E (Az.134°)

69.01

10" Poplar (27463 cap & nail in East face, set above found witness 8)

60.10

Wolm. 4x4 Phone Ped. Post (27463 cap & nail in NE corner)

S13°E (Az.167°)

94.65

Power Pole (27463 cap & nail in West face)

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983



SECTION

EMMET COUNTY REMONUMENTATION PROGRAM

CHRONOLOGY OF GLO CORNER

REMON. CORNER # 189

LCRC # 36-05-M9 TOWNSHIP...PLEASANTVIEW

CORNER COMMON TO SECTIONS 24/25, T36N, R5W

DATE	GLO	FOUND/SET Set Post	WITNESSES				
1840			1) S42°E 2) N10°W	32 lks. 30 lks.	10" Bee		
1879	L. Hartzler County Surveyor Pleasantview Tw	Stone p. Highway Records Pgs. 7	No Witnesses				
1978	R. E. Bidstrup Survey Map L. 285, Pg. 829	Set 5/8" Rerod	3) S40°E 4) N40°W 5) East	65.83' 47.56' 50.04'	16" Aspen Fence Post Spike		
1990	M. Trowbridge Survey Map	Found 1/2" Rerod	6) S36°E (az. 7) S66°E (az. 8) S46°E (az. 9) N22°W (az	114°) 134°)	43.87' 82.92' 68.97' 51.6'	4" Tele. Post 6" Poplar 6" Poplar Stop Sign	
1990	M. Trowbridge LCRC L. 2, Pg. 315	Found 1/2" Rerod (Record of 1990 Rerod)	6) \$36°E (az. 7) \$66°E (az. 8) \$46°E (az. 9) N22°W (az	114°) 134°)	43.87' 82.92' 68.97' 51.6'	4" Tele. Post 6" Poplar 6" Poplar Stop Sign	
1992	J. E. Young Survey Map L. 506, Pg. 581	Found 5/8" Rerod	3) S40°E 4) N40°W 5) N90°E	65.83' 47.56' 50.04'	16" Aspen Fence Post Spike		

