







STATE OF MICHIGAN EMMET COUNTY: RECORDED

APR 2 9 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE DEC 22 AM 8: 44

42. 42. 44. 1	AISSION Filing F	Requirement of Act 74, Mich.	P.A. 1970/	
For corners in Emmet			Alema a Signer	
(County)	Located In:	Corner Code ≠	REGISTER OF DEEDS	
1. Public Land Survey E.C.R.P. # 92			LIBER <u>A</u> PAGE <u>99</u>	
 Property Controlling in Section Miscellaneous Property in Sec. 	T R _ S T R _ S T R _ S T R _		PAGE 77 Register of Deeds Stamp & File No	umber
4 Lot No	Recorded Plat	444	A B C D E F G H I	
I. Thomas D Swenor do hereby certify that under rein lines 1 and 2 above were current manual of survey instrument or by a decree of above were in conformance were in conformance were stablished, expressed below: NOTE: Not more than 4 con this certificate A. Description of original C11, Section Corner comm	in a field survey on	gan P.A. of 1970, the corner points mer tions and rules therefore as required as Department of the Interior, Bureau one corner points mentioned in lines 3, 18 Board of Land Surveyors or by a Decied, re-monumented, recovered, four town and range, may be recorded ries and/or subsequent restoration	2	-2 -11141 -23262 -3535
(SEE BACK OF P	AGE FOR HISTORY)		Emmet County R.E. GLUE 18 DEC. 19915	
B. Description of corner	evidence found and/or m	nethod applied in restoring or ree	stablishing corner:	
recorded in Liber 1, I B. Jones in 1989, and went to comer location but clean fill sand below post. THIS CORNER IS A	Page 19. Corner found by 1 Trowbridge in 1990, as reon. Removed monument low. Iron falls in a cut area.	Green in 1972. Said pipe recorded Bidstrup in 1972, C.E. Ostling in 1: ecorded in LCRC Liber 2, Page 320 box and 1" pipe and dug 36" below a, and there is no evidence with reg	977, Green in 1982, On 11-28-95 ricon. Found nothing ards to GLO witnesses	
		N OF THE ORIGINAL CORNER.	locating the position of the corner:	
CH, Found I" diameter. l	[8" long pipe in monumen	at box and replaced with a 2" diamenter County Remonumentation Cap	ter, 30" Long PVC Pipe	Manney St.

NAMES AND ADDRESS OF THE PROPERTY OF THE PROPE

(6) 10" Spruce - N54°E 66.55' (spike nail in west face)
(8) 10" Hemlock - S73°W 76.35' (spike nail with die cap in south face)

(9) 12" Popular - S52°E 80.70' (spike nail in south face)
 (10) Power Pole - N63°W 77.25' (p.k. nail)

Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1987

SWENOR

77282 CAND SURVEY

37282

LIBER A

A. Description of original monument and accessories and/or subsequent restoration

Date	Surveyor	Found	(Witr	iesses)
1840	GLO	Set Post	(1) (2)	Beech 8 S68W 18 Hemlock 12 N47E 37
1878	John Keep	Field notes and minutes of highway survey, Commencing at the NE Corner of the NW 1/4 of Sec 34, 36-4 and running west along section line between Sec 33 & 28, and 32 & 29, and 31 &30 to the NW Corner of Sec. 31.		
1972	Green	Found 3/4" Pipe	(3) (4)	Tele Pole N60E 58.53' 6" Hemlock N28W 94.40' (UNRECORDED SURVEY) (RECORDED L.1, P.19, LCRC)
1972	Bidsrtup	Found 1/2" Pipe	(3) (4) (5)	Tele Pole N61E 58.51' 6" Hemlock N28W 94.37' 4" Aspen S65E 79.05'
1977	C.E.Ostling	Found Corner	No ca	ll for type of iron, or witnesses
1982	Green	Found 3/4" Pipe in monument box	(3) (4)	Tele Pole N60E 58.53' 6" Hemlock N28W 94.40' (UNRECORDED SURVEY)
1989	B. Jones	Found 3/4" Pipe	(6) (7) (8) (9)	10" Spruce N54E 66.55' 10" Tamarack N25W 93.30' 14" Spruce S73W 76.35' (witness is Hemlock 10" Poplar S52E 80.70' (RECORDED SURVEY L.448,P.089)
1990	Trowbridge	Found 1" Pipe in monument box	(3) (9) (8) (10)	Utility Pole Az 62 58.28' 8" Poplar Az 127 80.65 8" Hemlock Az 250 76.30' Power Pole Az 327 77.25' (RECORDED SURVEY L.439,P.093) (RECORDED L.2,P.320, LCRC)