SUNVEY & REMONUMENTATION

MAY 05 1997

COMMISSION

STATE OF MICHIGAN EMMET COUNTY RECORDED

96 DEC 31 PM 2: 21

Market -

		LAND CORN	ER RECORDATION CERTIFIC	CATE		111 6: 24
Fo	r corners in	Filing Requi	rement of Act 74, Mich. P.A.	1970	Lanner.	Edin
-	EMME	Located In:	Corner Code ≠#		REGISTER of	PEFDE
	Public Land Survey E.C.R.P#1	T R	G-13 JA.K.A		ER Page	<u>A</u>
2.	Property Controlling in Section	S T R S T R			1	A.
3.	Miscellaneous Property in Sec.	S T R S T R		Registe	er of Deeds Stam	p & File Numb
		corded Plat			A B C D E F	G H I J I
				2	1 7 1 7 1 7	
do in I cur Ma abo Cor exp	hereby certify that under requires 1 and 2 above were in order manual of survey instructionagement or by a decree of a cover were in conformance with urt of Law; established, repressed below:	irements of P.A. 74, Michigan P.A. conformance with regulations a ctions of the United States Depa Court of Law and/or that the correthe rules of the Michigan Board-established, monumented, re	A. of 1970, the corner points mentione and rules therefore as required in the interior, Bureau of Lander points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found as	ne 7 1d 7 5 8 a 9	-19 -20 -21 -30 -29 -28	15 14
NC	OTE: Not more than 4 cor on this certificate.	rners, all in the same town a	and range, may be recorded	11		3435-
A.	Description of original m	onument and accessories ar	nd/or subsequent restoration:	13	L	
	and Section 3, and Section	to Section 33,and Section 34' on 4, T36N R4W AGE FOR HISTORY)	137N R4W			
В.	Description of corner evi	dence found and/or method	applied in restoring or reestabli	shing cor	ner:	
	G-13, Found 3/8" Pin, inside of 3/4" Pipe. Found 3/4" Pipe above 1-1/2" Cast Iron Pipe. Found 1-1. Cast Iron Pipe inside an extremely rotten cedar post. Very little remaining of cedar post, but enough left to determine that pipe appears to have been set inside the cedar post. 1-1/2" Pipe very much resembles pipes found at D-13, and E-13. THIS CORNER IS ACCEPTED BY THE EMMET COUNTY REMONUMENTATION GROAS A FAITHFUL AND CAREFUL PERPETUATION OF THE ORIGINAL CORNER.				APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County R.E. CLUES	
C.			established to perpetuate locat		12-30-96	er:
O .	G-13, Found 3/8" pin, inside 3/ inside an extremely old of Pipe with a Base magnet Cap. Further set a monu Witnesses: (3) N51°W 54.84' - Soo (6) S56°W 37.54' - Pov (7) N67°W 87.30' - Pov	4" Pipe, which is above 1-1/2" sedar stake, and replaced with and a standard Brass Emmet ament box to preserve corner patheast Corner Sidewalk (formover Pole (found spike nail) wer Pole (found spike nail)	Cast Iron Pipe, which is a 2" diameter, 30" long PVC County Remonumentation position.	Total Halling Street West College	*******************************	Anna astronomical de la constante de la consta
	(8) S39°W 55.20' - 8" J	ack Pine (found spike nail)			THE LAND	ı -

LIBER A
PAGE 146

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 116 T37N R4W - G-13

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

Date	Surveyor	Found	(Witnesses)		
1840	GLO	Set Post Corner	(1) (2)	Beech 6 - N38E 37 Beech 6 N77W 11	
1892	S.G.Main	Set Large Cedar Post 8" Dia., 3-1/2' Long			
1893	S.G.Mam	Set 7" Cedar Post, 4 fee surface.	t long, 6" Below	Set cedar posts @ angles of 45°, N45°E N45°W, S45°E, S45°W at outside Hwy. Limits.	
1916	S.G.Main	T-Rail 5-1/2' Long at above 1892 Position			
1957	E.C.R.C.	Found survey stake	(3) (4) (5)	54.8' - S.E. Corner McRae Sidewalk S.E. 35.7' - Telephone Pole 55.7' - East Corner McRae Vault	
1963	Schweigert & Young	Found 3/4" Iron Pipe		no witnesses	
1969	R.E.Bidstrup	Corner noted as found		no witnesses	
1969	J.H.Green	Corner noted as found		no witnesses	
1969	G.E. Young	Found 3/4" Pipe		no witnesses	
1972	G.E.Young	Found 3/4" Pipe		no witnesses	
1973	J.H.Green	Found 1/2" Re-rod	(4) (3)	S.E. 35.7' - Telephone Pole 54.8' - S.E. Corner McRae Sidewalk	
1979	R.E.Bidstrup	Found Iron Pipe	(3) (4) (5)	54.8' - S.E. Corner McRae Sidewalk S.E. 35.7' - Telephone Pole 55.7' - East Corner McRae Vault	
1983	J.H.Green	Found Iron Pipe	(4) (3)	S.E. 35.7 - Telephone Pole 54.8' - S.E. Corner McRae Sidewalk	
1984	J.B.O'Neill	Found 3/8" Pin in pvt.	•	no witnesses	
1992	T.D.Swenor	Found 1/2" Re-rod	(4) (3)	S.E. 35.7 - Telephone Pole 54.8' - S.E. Corner McRae Sidewalk	
1992	M.A.Trowbridge	Shows corner as found		No witnesses. Survey rec. L.475, P.172	
1993	Farrier	Found 1/4" Iron Pipe at T-Intersection	(6) (7) (8) (3) (9)	S57°W 37.58' - Power Pole N67°W 87.37' - Power Pole S40°W 55.22' - 7" Scotch Pine N50°W 55.00' - S.E. Corner McRae Sidewalk S75°E 131.91' - Power Pole	
1995	R,E.Oelke	Found 1/4" Iron Pipe @) McRae St		