

SECTION

V. N. 2000.

SUSSEEN

LAND CORNER RECORDATION CERTIFICATES DEC 30 PM 12: 00

	Filing Requirem	ent of Act 74, Mich. P.A. 19	70
For corners in EMMET	Located In:	Corner Code #	Glenna a. Sijac
(County)			REGISTER OF DEEDS
1. Public Land Survey ECRP #180 2. Property Controlling in Section	T_37N R_5W T R T R T R S T R S T R	G2	PAGE 252
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
I. Michael A. Trowbridge do hereby certify that under rementioned in lines 1 and 2 at required in the current manual of Bureau of Land Management of mentioned in lines 3, 4 and 5 a Professional Surveyors or by a fire-monumented, recovered, found this certificate. A. Description of original means the service of the ser	bove were in conformance with f survey instructions of the United or by a decree of a Court of La above were in conformance with Decree of a Court of Law; establi	er 22 , 19 98 , n P.A. of 1970, the corner point regulations and rules therefore a d States Department of the Interio aw and /or that the corner point the rules of the Michigan Board of ished, re-established, monumented drange, may be recorded	16 6 18 - 17 - 16 - 15 14 13 14 13 15 16 8 19 20 - 21 22 - 23 24
	BACK OF THIS FORM FOR CO	APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County R.E. Cleure, P.S., E.C. Rep. 29 DEC. 1998	
B. Description of corner evi	idence found and/or method a	applied in restoring or reestablis	shing corner:
G2, CORNER COMMON	TO SECTIONS 3, & 4, T37N,	, R5W	
Found 1/2" rerod at inter	section of gravel roads (Canb	y Rd. north and south, and Pyj	ar Rd. to the east).
Witnesses I	Found		

3) S58°W (Az.238°) 42.35' 4) N30°W (Az.330°) 71.18'

Fence Post

5) N47°E (Az.47°)

Power Pole

44.73' Corner Fence Post

Spike in above witnesses

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G2, CORNER COMMON TO SECTIONS 3, & 4, T37N, R5W

The 1/2" Rerod noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program cap. This position is accepted as the best available evidence of the position of the original corner.

ADDITIONAL NEW WITNESSES:

\$50°E (Az.130°)

79.35' 6" Cedar (27463 cap & nail in South face)



Signed by Michael a. Irmbridge	Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 27463 Surveyor's Michigan License No.____

SECTION

136:37 <u>4</u> PAGE <u>353</u>

EMMET COUNTY REMONUMENTATION PROGRAM

CHRONOLOGY OF GLO CORNER

REMON. CORNER # 180

LCRC # 37-05-G2 TOWNSHIP...CENTER

CORNER COMMON TO SECTIONS 3/4, T37N, R5W

DATE	SURVEYOR	FOUND/SET	WITNESSES			
1840	GLO	Set Post	1) S15°W 18 lks.		8" Sugar	
			2) S18°E	57 lks.	12" Sugar	
1989	M. Trowbridge	Set 1/2" Rerod over	3) S58°W (az	. 238°)	42,35'	Fence Post
	Survey Map			. 330°)	71.18'	Power Pole
	• •	line west.	5) N47°E (az. 47°) 6) S46°E (az. 134°)		44.73'	Cor. Fence Post
					52.98'	6" Poplar
1989	M. Trowbridge 1/2" Rerod		3) S58°W (az. 238°)		42.35'	Fence Post
	LCRC	(Record of 1989 Rerod)	4) N30°W (az. 330°)		71.18'	Power Pole
	L. 2, Pg. 297	•	5) N47°E (az.	47°)	44.73'	Cor. Fence Post
	, ,		6) S46°E (az.	134°)	52.98'	6" Poplar
1997	J. H. Granger	Found Iron	Witnesses as recorded in			
	Survey Map L. 604, Pg. 48	with cap #27463	Liber 2, Page 297			

