SURVEY & REMOMBENTATION

MAR 1 3 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN EMMET COUNTY RECORDED
MARTHED

99 DEC 28 AM 9: 35

12

13

25

36

14

For corners in	Filing Requiren	nent of Act 74, Mich. P.	
EMMET (County)	Located In: READMOND	Corner Code # TOWNSHIP	Allenna A. Sier REGISTER OF DEFOS
1. Public Land Survey ECRP #197	T <u>37N</u> R <u>6W</u>	<u>l-3</u>	LIGER A
2. Property Controlling in Section	S T R S T R		PAGE 308
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Re	corded Plat		
5. Private Claims			
			ABCDEFGHIJKLM

3

5

6

7

9

10

11

..1¹0

30.-

-31

28

OF MICH

RICHARD E **OELKE** PROFESSIONAL

SURVEYOR 33983

27.

I, <u>Richard E, Oelke</u>, in a field survey on <u>10 December</u>, 19 <u>99</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO set corner in 1840's. Trowbridge found 3/4 pipe, Abstract: set by persons unknown, and accepted it as the corner. It has been used in subsequent surveys by local surveyors.

See back page for chronological history of corner.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Poressio 1/2" iron pipe, set by persons unknown, 2' south of centerline of Division Road, at approximate centerline of Cemetery Rd. to the north, approximately 33' north of old E&W ROW fence to the S.

> 1) N37°E. 44.63',

2" steel post

2) N50°E. 55.09',

pp, cap #27463 SE face

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set: The 1/2" pipe noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program Cap, which was placed within a standard monument box. This position is accepted as a careful and faithful perpetuation of the position of the original corner.

Additional New Witnesses:

S 80° E, 188.77', S 03° W, 32.6', S 30° W, 36.24',

pp, tagged 33983 in S face bent fence post, with very old tag

2'x2'x2' granite boulder with new "x" chisled on top

N 81° W. 233.291, pp, tagged 33983 in SW face

> Date 10 December 1999

APPROVED LAND CORNER P.A. 345 OF 1990

Emmet County

ECRP. RED

SUNVEY & REMONUMENTATION

MAR 1 3 2000

SECTION

PAGE 309

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 197

37-6-13

T37N R6W corner bet. Secs. 2,3,10, &11 DIVISION ROAD, and UNNAMED ROAD NORTH

<u>Date</u>	Surveyor	Found	Witnesses	Notes		
1840	GLO	Set post		"Beech		
1990	Trowbridge	LCRC (L2-31	17), fd +/-3/4" pipe, at road in 1) N43°E, 44.50', 2) N56°E, 55.05', 3) S57°W, 50.35',	2" steel post pp, cap #27463 SE face		
1991	Swenor	fd. 3/4" pipe	e, as witnessed above			
1992	O'Neill	fd. ½" pipe, 1' south of centerline pavement				
1993	Trowbridge	fd. 3/4" pipe				
1997	Granger	fd. 3/4" pipe, as witnessed above				
1998	Oelke	fd. ½" pipe, as witnessed above				