## 1998 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970					
For corners in				MASTER 4013 PAGE	112
Genesee County Loc	cated In:	Corner Code #		in:	مهيئة بالاستناف
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	T <u>5NR6E</u> TR TR TR	D-5 SUNTY SMONTAMENT - MAR 17 199	S ALLOM	106840 Register of Deeds S	ramp & File
4. Lot No, Recorded Plat 5. Private Claims		SECTION	_	A B C D E F G	H I J K L M
I, Kevin B. Cleaver, in a field survey on Cof P.A. 74, Michigan P.A. of 1970, the corner pwith regulations and rules therefore as require States Department of the Interior, Bureau of Lathe corner points mentioned in lines 3, 4 and Board of Land Surveyors or by a Decree of recovered, found as expressed below:  NOTE: Not more than 2 corners, all is on this certificate.	October 21, 1998, opinis mentioned in lined in the current mand Management or by 5 above were in configuration of Law; est	nes 1 and 2 above were nual of survey instruction y a decree of a Court of low formance with the rules lablished, re-established	in conformance as of the United Law and for that of the Michigan , monumented,	5	-
A. Description of original monument and	d accessories and/o	or subsequent restora	tion:		
4-15-1823 General Land Office (GLO Undated Gould Engineering, Inc. (GE 8-22-1958 recorded plat of "McCubbin 1965 GEI records: iron w/four access Undated GEI records: pipe w/four access-12-6-1978 Land Corner Recordation (accessories)	l) records: iron, p n Acres No. 1": d sories cessories	oipe, and four acces imensioned to quar	sories ter corner	STATE OF THE STATE	The II In
B. Description of corner evidence found	l and/or method ap	plied in restoring or re	establishing cor		25
GLO corner and accessories not foun Recovered two accessories from first Confirmed within acceptable tolerance Recovered one accessory from 1965 Recovered one accessory from secon Recovered corner as identified and the The monument found was ratified by the October 14, 1998	set undated GEI e 1958 platted me GEI records nd set undated GE ree accessories f	easurement to quarte El records from 1978 LCRC		SEEDS NTY	H 19A
C. Description of monument for corner at	nd accessories esta	ablished to perpetuate	locating the pos	sition of the corner:	
Set in concrete the standard Bernstein Remonumentation Corner, 1998, #292 NORTH 50.18' set Genesee County V N 45° E 53.89' to top center of easterl S 15° E 36.10' set Genesee County V SOUTH 33.08' set Genesee County V Signed by	242" in monumen Vitness tag in top y gate post set in Vitness tag in wes	t box over 1/2" reroo of ROW marker concrete t face 42" oak		mped "Genesee County Ratified by Pecaccordance with P Co. Rep. 10-14- 12/8/98	
Kevin Banfield Cleaver, P.S.	KEV. BANFIELD (				
Surveyor's Michigan License No. 29242 рдг/ьь 98-дскм-рдк-2809	BANFIELD OF PROFESS SURVE	SIONAL YOR APPR	ROVED BY MICHIGAN	STATE BOARD OF PROFESSIONAL SU	IRVEYORS, JAN. 28, 19 REVISE AY 14,19' REVISED JAN., 19: REVISED OCT., 19: