1998 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

والأوان

For corners in Corner Code # Located In: Genesee County T5N_ R6E 1. Public Land Survey 2. Property Controlling 106835 in Section 3. Miscellaneous Register of Decds Stamp * File Number Property in Sec. 1. M _, Recorded Plat SECTION 4 Lot No. 5. Private Claims I, Kevin B. Cleaver, in a field survey on October 22, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree . 15 of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 24 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 4-15-1823 General Land Office (GLO) fieldnotes: set post w/ two accessories

Undated Gould Engineering, Inc. (GEI) records: stone w/six accessories Undated GEI records: 1 1/2" pipe w/seven accessories 4-13-1961 recorded plat of "Walnut Grove Estates" dimensioned to quarter corner 1965 GEI records: iron w/three accessories 4-30-1990 PA 132 Certified Survey, Liber 2392, Page 160: 1/2" rerod in monument box w/five accessories 8-21-1990 Land Corner Recordation Certificate (LCRC), Liber 2472, Page 253: 1/2" rerod in monument box 8-28-1990 LCRC, Liber 2415, Page 44: 1/2" rerod w/cap #14093 in monument box w/five accessories Recorded plat of "Loon Lake Estates": dimensioned to quarter corner 5-10-1995 GEI records: 1/2" rerod in monument box w/four accessories

Description of corner evidence found and/or method applied in restoring or reestablishing corner: GLO corner and accessories not found Corner and accessories from first set undated GEI records not found Recovered one accessory from second set undated GEI records Confirmed within acceptable tolerance 1961 platted measurement to quarter corner Recovered one accessory from 1965 GEI records Recovered corner as identified and three accessories from 1990 survey Recovered corner as identified and two accessories from 8-21-1990 LCRC Recovered corner as identified and two accessories from 8-28-1990 LCRC

The monument found was ratified by the Genesee County Remonumentation Peer Review Committee on October 14, 1998

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set in concrete the standard Bernsten monument SS-A-5BR-30 with 3 1/4" brass cap stamped "Genesee County

Remonumentation Corner, 1998, #29242" over 1/2" rerod in monument box.

N 35° E 49:82' found nail/tag #32332 in southeast face power pole

Confirmed "Loon Lake Estates" platted measurement to quarter corner Recovered corner as identified and three accessories from 1995 GEI records

S 53° E 59.90' found concrete monument

S 62° W 90.20' set chiseled "x" in north rim sanitary sewer manhole

N 37° W 69.60' set Genesee County Witness tag in southwest face power pole Tagendo F M

Ratified by Peer Group in accordance with P.A. 345, 1990

Date

Signed by Seura / Ban Kevin Banfield Cleaver, P.S.

NAME ZID CLEAVER PROFESSIONAL

Surveyor's Michigan License No. 29242

DGR/bb 98-GCRM-DGR-2813

SURVEYOR No. 000000

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983

REVISED OCT., 1995