1998 GENESEE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

(3)

1. Public Land Survey 2. Property Controlling S T R S I Section S T R S I S I S I S I S I S I S I S I S I S	106830
2. Property Controlling STR	106830
3. Miscellaneous S T R REMONUNCATION Property in Sec. S T R REMONUNCENTATION WAR 1 7 1999	Register of Deeds ? "amp & File Number
4. Lot No, Recorded Plat	A B C P E F G H I J K L M
I. Kevin B. Cleaver, in a field survey on November 5, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded	1 2 6 5 4 3 2 1
on this certificate.	10. 30 · 29 · 28 · 27 · 26 · 25 · 11 ·
 A. Description of original monument and accessories and/or subsequent restoration: 4-15-1823 General Land Office (GLO) fieldnotes: set post w/two accessories Undated Gould Engineering, Inc. (GEI) records: iron w/five accessories Undated GEI records: 3/4" pipe w/six accessories Undated GEI records: corner unidentified w/six accessories Undated GEI records: corner unidentified w/six accessories 2-24-1965 recorded plat "Thompson Commercial Sites": dimensioned to Corner I-2 9-17-1973 Land Corner Recordation Certificate (LCRC), Liber 1868, Page 539: iron in raccessories 3-8-1983 LCRC, Liber 2205, Page 355: monument box w/three accessories 3-8-1983 LCRC, Liber 2276, Page 380: monument box w/three accessories 3-4-1988 PA 132 Certified Survey, Liber 2321, Page 153: monument box w/three accessories 3-4-1986 LCRC, Liber 3440, Page 576: 1/2" rerod in monument box w/four accessories B. Description of corner evidence found and/or method applied in restoring or reestablishing or GLO corner and accessories not found Corner and accessories on all three sets undated GEI records not found Confirmed within acceptable tolerance 1965 platted dimension to quarter corner Recovered corner as identified and two accessories from 1973 LCRC Recovered corner as identified and two accessories from both 1983 LCRC Recovered corner as identified, two accessories, and confirmed dimension to quarter corner 	ssories and dimensioned I I I I I I I I I I I I I I I I I I I
survey Recovered corner as identified and four accessories from 1996 LCRC	
The monument found was ratified by the Genesee County Remonumentation Peer Review Committee on November 4, 1998	
C. Description of monument for corner and accessories established to perpetuate locating the particles.	
Set in concrete the standard Bernsten monument SS-A-5BR-30 with 3 1/4" brass cap si Remonumentation Corner, 1998, #29242" over 1/2" rerod in monument box. N 55° E 87.99' found nail/tag #35992 in southeast face power pole	Ratified by Peer Group in accordance with P.A. 345, 1990
S 34° E 58.58' found nail/tag #32332 in southwest face power pole S 45° W 77.34' northeast face of 8" diameter metal sign post for "B.P." gas station N 38° W 75.56' found nail/tag # 32332 in south face power pole	Co. Rep. 1 - 4 - 98
Signed by Econ Banfiel Aller Date Date	17/8/98
Kevin Banfield Cleaver, P.S. Surveyor's Michigan License No. 29242 DGR/bb 98-GCRM-DGR-2800 KEVIN BANFIELD CLEAVER PROFESSIONAL SURVEYOR No. 29242 REVISED MAY 14.195 REVISED OCT., 198	