COMPLET

Private Claims


Fi


	R RECORDATION CERT		1 1 (1)
ling Requirement of Act 74, Mich. P.A. 1970			•
	0	İ	

For corners in	•		
Genesee	Located In:	Corner Code ≠≠	
Public Land Survey	т <u>б</u> N <u>в 5</u> E.	C-4	
	T R		S. S.
2. Property Controlling in Section	S R		81559 a
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number


I. Kevin B. Cleaver, P.S., in a field survey on do hereby certify that under requirements of P.A. 74, Mid in lines 1 and 2 above were in conformance with regressions of the United States.	chigan P.A. of 1970, the ulations and rules the ates Department of the	corner points mentioned refore as required in the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that	at the corner points mer	ntioned in lines 3, 4 and 5
above were in conformance with the rules of the Michig	jan Board of Land Surv	eyors or by a Decree of a
Court of Law; established, re-established, monume	ented, re-monumented	d, recovered, found as

, Recorded Pial ____






May, 1823, GLO	Set post, no accessories
June 20, 1968	Recorded plat of "Duffield Meadows", plat mons.
Oct., 13, 1982	Survey by Elbex Harris, P.S. #9431
April 26, 1994	Certified survey, Liber 2543, Pages 86-88; RRS in
· · · · · · · · · · · · · · · · · · ·	pavement, with six (6) accessories



10

10



- Description of corner evidence found and/or method applied in restoring or reestablishing corner
 - Found railroad spike in pavement, fits the found monumentation of the 1968 plat of "Duffield Meadows"; found six(6) of the accessories from 1994 survey Liber 2543, Pages 86-88.

The monument found was ratified by the Genesee County Peer Review Committee on January 3, 1996. This monument is to be set with the 1996 remonumentation corners due to the existing frost conditions.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set in concrete the standard Bernsten monument SS-A-5-BR-30, with 3 1/4" brass cap stamped Genesee County Remonumentation Corner 1995; #29242 over a railroad spike in pavement.

Tare to a	البطاعدات وجواج	والمرابع المرابع المراجع المرابع المراجع المراجع والمراجع والمراع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراع و
N 85° E	26.62'	Found top center west edge I-beam post
S 60° W	25,45'	Found top center east edge I-beam post
S 60° E	31.10	Found top center west edge I-beam post
N 65° W	23.36'	Found top center east edge I-beam post

es in legists due to an existing CMP running under the road. NOTE: This monument is six (6)

Kev in Banfield Cleaver P.S Surveyor's Michigan License No. 29242

DUNE 14, 19960 : Date.