

MAY 20 1997

COMMISSION

1996 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Genesee (County) Located In: Corner Code #1

- 1. Public Land Survey T 6N R 5E C-5
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. Recorded Plat
5. Private Claims

RECORDED
DEC 19 10 14 AM '96

81558

Register of Deeds Stamp & File Number

I, Kevin B. Cleaver, P.S., in a field survey on June 3, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Grid with columns A-M and rows 2-13. A dot is marked at row 5, column C.

A. Description of original monument and accessories and/or subsequent restoration:

- May 22, 1983, GLO Set post with two (2) accessories
July 17, 1974 L.C.R.C., Liber 1899, Page 7, found steel bar, with three (3) accessories
October 13, 1982 Survey by PS #9431, found 1" square bar with three (3) accessories from 1974, L.C.R.C.
April 28, 1994 Certified survey, Liber 2543, Pages 86-88, found 1" hex bar, with one (1) 1974 and 1982 accessory, with four (4) new accessories

Ratified by Peer Group accordance with P.A. 345, Co. Rep. [Signature] Date Jan 3, 1996

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" square iron bar; found four (4) accessories from 1974 L.C.R.C.; found three (3) accessories from 1982 survey; found five (5) accessories from 1994 certified survey.

The monument found was ratified by the Genesee County Peer Review Committee on January 3, 1996. This monument is to be set during the 1996 program, due to the existing frost conditions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set in concrete the standard Bernsten monument SS-A-5-BR-30, with 3 1/4" brass cap stamped Genesee County Remonumentation Corner 1995, #29242 over found 1" square iron bar.

- S 45° E 94.80' Northwest corner of church
N 45° E 36.16' Nail/washer #10057 in southeast face of power pole
S 75° W 52.25' North edge of stop sign post
N 65° W 43.30' South face of 2" steel fence post
N 25° W 50.50' East face of 2" steel fence post

Signed by Kevin Banfield Cleaver, P.S., 1st Field Manager
Surveyor's Michigan License No. 29242



Date JUNE 3, 1996