SURVEY& REMONUMENTATION MASTER 3685 PAGE MAR 0 5 1998 REGIS A 10 1 11 az M '97 SECTION 1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 HESEE COUNTY For corners in REGISTER D Located In: Corner Code # <u>Genesee</u> (County) 1. Public Land Survey T 6N R 7E Register of 2. Property Controlling L M in Section 3. Miscellaneous Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims I, <u>Kevin B. Cleaver</u>, in a field survey on <u>October 28</u>, 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, reestablished, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Set post and two (2) accessories 1823 GLO Stake, four (4) accessories Date? **GEI** Stake, four (4) accessories **GEI** Date? CPCo Angle G-4, G-3, H-3 was 89°35'05" Oct. 1966 GCRD LCRC, L 2493 P 841, Found 1 1/2" Solid Rod in Monument Box, four (4) accessories April 9, 1993 GCRD LCRC, L 2598, P 194, Found 1 1/2" Solid Rod in monument Box, four (4) accessories May 4, 1995 Recorded Plat of "Heather Hill", L 71 P 1, 2, 3 and 4 April 8, 1996 Recorded Plat of "Heather Hill No. 2", L 71, P 46, 47, 48 and 49 Jan. 13, 1997 Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1 1/4" Rod in Monument Box Found angle G-4, G-3, H-3 and distances G-3 to G-4 and G-3 to H-3 from October, 1966 C.P.Co. records: Found four (4) accessories from April 9, 1993 LCRC L 2493 P 841; Found four (4) accessories from May 4, 1995 LCRC L 2598 P 194; Found plat monumentation in the recorded plat of "Heather Hill" L 71 P 1 - 4 April 8, 1996; Found plat monumentation in the recorded plat of "Heather Hill No. 2" L 71 P 46 - 49 January 13, 1997. The monument found was ratified by the Genesee County Peer Review Committee on October 30, 1997, as the accepted corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set the standard Bernsten monument SS-A-5-BR-30 with 3 1/2" brass cap stamped Genesee County Re-monumentation Corner 1997, #29242 in concrete over a 1 1/4" rod in a monument box. Ratified by N 45° W, 61.65' - Found Nail and Tag in the Northeast face of a power pole Peer Group in S 40° E, 70.52' - Found Nail and Tag in the Northeast face of a power pole accordance with P.A. 345, 1990 S 50° W, 70.38' - Found Nail and Tag in the Southeast face of a power pole N 60° E, 63.48' - Found Nail and Tag in the Northwest face of a power pole E OF MICH 10-30 BUNEST BOLE (VEB Signed by **PROFESSIONAL** Kevin Banfield Cleaver, SURVEYOR Field Manager

No. 29242

OFESSIO

8856**1**

97H-GCRM-LCRC-3511

Surveyor's Michigan License No. 29242

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975

REVISED JAN., 1983 REVISED OCT., 1995