MASSTER 3685 PAGE 949

11 33 M '97

MAR 0 5 1998

SECTION 19	97 REMONUMENTAT	ION PROGRAM	f		•		
For corners in	iling Requirement of Act	74, Mich. P.A. 1970	GENESE	E COUNT	17		
Genesee (County)	Located In:	Corner Code #		, <u>, , , , , , , , , , , , , , , , , , </u>	, · · -		
1. Public Land Survey	T <u>6N</u> R_7E T R	G-4		100	10.		
2. Property Controlling in Section3. Miscellaneous Property in Sec.	TR S TR S T R S T R		Regis	ter of Deeds	A	Number H I J K	
4. Lot No, Record	ed Plat		4 5 6	18-17-	9_	1.0 11	
in conformance with regulations instructions of the United States De of a Court of Law and /or that the own the rules of the Michigan Board ished, monumented, recovered	epartment of the Interior, Bureau of printer points mentioned in lines 3, for Land Surveyors or by a Decre ed, found as expressed below:	In the current manual of I in the current manual of of Land Management or by a 4 and 5 above were in confo- e of a Court of Law; establish	ve were survey decree rmance ned, re-	-1,g -20-	21 28 2	23 23	-2
NOTE: Not more than 2 corr on this certificate.	ers, all in the same town an	d range, may be recorde	13	31 32	33 3	35	1
A. Description of original monu	ment and accessories and/or	subsequent restoration:					
1823 GLO Set r. Date? GEI Stone Jan. 28, 1942 GCRD Record Oct. 26, 1966 CPCo G-4 t Jan. 5, 1973 GEI Foun March 24, 1981 GEI Angle 1993 GEI Foun	post and two (2) accessories e/Pipe, four (4) accessories orded Plat of "Jefferson Acre o G-3 recorded as 2639.10 d 3/4" Iron Rod in Pavemer e F-3, G-3, G-4 recorded as d 3/4" Rod in Pavement, for d 3/4" Rod in Monument Bo	s es" L19, P 53 ' nt, five (5) accessories 89°11'45"					
B. Description of corner evidence	ce found and/or method applic	ed in restoring or reestabli	shing corner:				
Found 3/2" Rod in Pipe			•				
Found distance G-3 to G-4 distance G-4 to G-3 and ar accessories from January Found two (2) accessories records.	in the recorded plat of "Jef ngle G-4, G-3, H-3 from Oct 5, 1973 GEI records; Found from 1993 GEI records; Fo	toner 26, 1966 C.P.Co.	records; Fou	ind two (2)	•		
the monument found was accepted corner.	ratified by the Genesee Cou	unty Peer Review Com	mittee on No	vember 13,	1 9 97, as		
. Description of monument for co	orner and accessories establis	hed to perpetuate locating	the position	of the corner			
Set the standard Bernsten r Re-monumentation Corner	Manument SS A E pp. aa	41 o 440 i		e County	•		
Most 49 202 Face 134 #				hv Be	ar Greu	n la	

West, 48.28' - Found Nail and Tag in the East face of a power pole S 15° E, 59.87' - Found Top of Hydrant N 70° E, 42.68' - Found Nail and Tag in the West face of a 10" Spruce East, 6.86' - Found Back of Curb

В.

accordance with P.A. 845

Kevin Banfield Cleaver, Field Manager

Surveyor's Michigan License No. 29242

97H-GCRM-LCRC-3618

PROFESSIONAL

SURVEYOR

No.

29242

0 = [\$ \$ 1 0

ROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975

REVISED JAN., 1983 REVISED OCT., 1995

88584