918 MASTER 3685 PAGE

For corners in Corner Code # Located In: (County)

2. Property Controlling in Section

I. <u>Kevin B. Cleaver</u>, in a field survey on <u>December 8</u>, 19 97 do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, resetablished, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set post and two (2) accessories Recorded Plat of "Bella Vista Estates No. 1" L 39 P 31 and 32 **GLO** 1823 LCRC, L 2448 P 742 - Found 'T' Iron #9431, four (4) accessories Dec. 19, 1963 GCRD LCRC, L 2520 P 754 - Found 'T' Iron #9431, four (4) accessories Jan. 2, 1991 Certified Survey, L 2524, P 749 - 753 - Found 'T' Iron #9431, four (4) accessories Dec. 17, 1993 Recorded plat of "Kirkridge Estates No. 4" L 69 P 15 and 16 Feb. 3, 1994 LCRC, L 2448, P 742 - Found 'T' Iron #9431, four (4) accessories **GCRD** Feb. 24, 1995 Recorded Plat of "Kirkridge Estates No. 5" L 70 P 12 and 13 LCRD, L 2448, P 742 - Found 'T' Iron #9431, four (4) accessories GCRD Aug. 11, 1995 GCRD Certified Survey, L 3491, P 887, 888 and 889 April 9, 1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 'T' Iron

Found plat monumentation in the recorded plat of "Bella Vista Estates No. 1" L 39 P 31 - 32 December 19, 1963; Found four (4) accessories from January 2, 1991 LCRC L 2448 P 742; Found four (4) accessories from December 17, 1993 LCRC L 2520 P 754; Found four (4) accessories and distance I-6 to I-5 from February 3, 1994 survey L 2524 P 749 - 753; Found four (4) accessories and plat monumentation from the recorded plat of "Kirkridge Estates No. 4" L 69 P 15 - 16 February 24, 1995; Found four (4) accessories and plat monumentation from the recorded plat of "Kirkridge Estates No. 5" L 70 P 12 - 13 August 11, 1995; Found distance I-5 to I-6 from April 9, 1997 survey L 3491 P 887 - 889.

The monument found was ratified by the Genesee County Peer Review Committee on December 11, 1997, as the accepted corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set the standard Bernsten monument SS-A-5-BR-30 with 3 1/4" brass cap stamped Genesee County Re-monumentation Corner 1997, #29242 over a 'T' Iron.

N 45° E, 4.43' - Found Nail and Tag in the Northwest face of a 6" tree

N 10° E, 27.36' - Found Nail and Tag in the West face of a 5" tree

South, 3.39' - Found North face of C.L.F. post

East, 35.81' - Found Nail and Tag in a 12" tree

Signed by Surv Kevin Banfield Cleaver, P.S.,

Field Manager

Surveyor's Michigan License No. 29242

97H-GCRM-LCRC-3645

BANFIELD CLEAVER **PROFESSIONAL** SURVEYOR No. 29242

0188510#

Ratified by Peer Group in accordance with P.A. 345, 1990

approved by Michigan State Board of Professional Surveyors, Jan. 28, 1971 REVISED MAY 14,1975

REVISED JAN., 1983 REVISED OCT., 1995

88553

11 32 M '97 DEC 23 1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 GENESEE COUNTY 3 odNRO T 6N R 7E 1. Public Land Survey Register of Deeds Stamp & File Number L M 3. Miscellaneous Property in Sec. _, Recorded Plat 4 1.ot No. 5. Private Claims

RECURDED