MAY 2 0 1997 1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code :## Genesee Public Land Survey **Property Controlling** in Section Miscellaneous · Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. . . Recorded Plat 5. Private Claims Kevin B. Cleaver P. S. a field survey on November 22 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: Set post with two (2) accessories 1821 GLO Michigan Department of Transportation construction plans Oct 11, 1930 Genesee County Road Commission Construction plans 1934 Gould Engineering, Inc. records, Nail in center line of road with three (3) accessories Date? LCRC Liber 2305, Page 497, with three (3) accessories July 3, 1986 Peer Group in Ratified by B. Description of corner evidence found and/or method applied in restoring or reestablishing accountdance with P.A. 345, 1990 Co. Rep. Date 10-15 We re-established the corner by using the three (3) accessories from the LCRC Liber 2305, Page 497. We found these ties to place the corner on the east town line T7N-R4E. We found this location to also fit the construction plans of 1930 and 1934. The method used to re-establish this corner was ratified by the Genesee County remonumentation committee on October 15, 1996 as the accepted corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set in concrete the standard Bernsten monument SS-A-5-BR-30 with 3¼ " brass cap stamped Genesee County Remonumentation Corner 1996, #29242 in a monument box. Southeast corner of east and west headwall S 45° E 53.70 Set remon tag in north face 14" Maple \$ 50° W 48.70' Set remon tag in north facuto a N 70° W 43.86 "oto pakt nalld" N 45° E Northeast corner 54.50' west headwall KEVIN

BANFIELD CLEAVER **CONDEESSIONAL**

No.

29242

kevin Banfield Surveyor's Michigan License No. DE PROPERTY SUPPLY

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ale NOV ZZ, 1996

REVISED JAN., 1903