MAY 2 0 1997

MASTER 3436 PAGE 813

AND	COU		 	 			ΤE	
		_		 	_	_	 	

For corners in Genesee		31/1/	ment of Act 74, Mich.	
		Localed In:	Corner Code =##	= 1
1.	Public Land Survey	T 7N R 5E T R T R	E-4	83536 96. III LE
2.	Property Controlling in Section	T R S T R S T R		. FUED WITH MINISTER S
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	Lot No, F	Recorded Plat	· .	A B C D E F G H + J K L

I, Kevin B. Cleaver, PS, a field survey on . October 18. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1821, GLO Set post, with two (2) accessories

Date?

GEI records, found rod, with five (5) accessories

July 2, 1971

July 2, 1971

Juney, Liber 1810, Pages 794 & 795, ½" iron pin with four (4) accessories

LCRC, Liber 1977, Page 796, found ½" iron pin, with three (3) accessories

Dec. 30, 1980

Survey, Liber 2104, Page 226, found iron pin with four (4) accessories

April 14, 1987

Survey, Liber 2305, Pages 492 & 493, found ½" re-rod, with three (3) accessories

April 14, 1987

LCRC, Liber 2305, Page 494, found ½" re-rod, with three (3) accessories

Nov. 30, 1993

Survey's Liber 2521, Pages 282 & 283; Liber 2525, Pages 680 & 681; Liber 2549, Pages 813 & 814, found ½" rod with four (4) accessories

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found $\frac{1}{2}$ " re-rod in gravel; found rod and one (1) accessory from GEI records date ?; found one (1) accessory from July 2, 1971, survey; found one (1) accessory from Jan. 19, 1977, LCRC; found one (1) accessory from Dec. 30, 1980, survey; found $\frac{1}{2}$ " re-rod and two (2) accessories from April 14, 1987, survey; found $\frac{1}{2}$ " rod and two (2) accessories from April 14, 1987, LCRC; found $\frac{1}{2}$ " rod and three (3) accessories from Nov. 30, 1993, survey's.

The monument found was ratified by the Genesee County Peer Review Committee on October 9, 1996, as the accepted corner. Ratified by Peer Group in

accordance with P.A. 345, 1990 Co. Rep. 10-9-96 Date _

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

KEVIN

A CONTRACTOR OF THE PARTY OF TH

Set the standard Bernsten monument SS-A-5-BR-30, with 31" brass cap stamped Genesee County Remonumentation Corner 1996 #29242 over a found ½" re-rod in gravel.

S 76° W 31.30' Found Cornerstone tag in North face power pole found Cornerstone tag in South face power pole Found pointed stone $2\frac{1}{2}$ high 24.22' East S 20° E 63.321 Set remon. tag in Northernoe of 6" elm 61.45' THE OF MILES

BANFIELD OF EAVED PROFESSIONAL **CURY YOU** Date OC Signed by Kevin Banfield Surveyor's Michigan License No. Cleaver,

10

12