

1998 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

KON HESEE HSTER  $\infty$ 윷 98

Genesee Located In: Burton Twp. Corner Code # E-13 (County)

1. Public Land Survey R<sub>7</sub>E E-13 101227 SURVEY & Register of Deeds Stamp & File Number REMONUMENTATION

2. Property Controlling in Section MAR 17 1999 3. Miscellaneous Property in Sec.

, Recorded Plat 5. Private Claims Gilbert G. Bonno, P.S.

, in a field survey on <u>September</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A B (	C D	E F (	∋ H ∈	I J K	LM
6	- 5	4	3	2	<b>]</b>
7	- 8	9	10	11	12
18	17	- 16	15	14	13
19	-20-	21	22	23	24
30	-29	- 28	27	26	25
31	32	33	34	35	36
	- 7 - 18 - 19	6 5 7 8 18 17 19 20	6 5 4 9 18 17 16 19 20 21 30 29 28	6 5 4 3 7 8 9 10 18 17 16 15 19 20 21 22 30 29 28 27	6 5 4 3 2 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

## A. Description of original monument and accessories and/or subsequent restoration:

1815 GLO - Alex Holmes, No description of monument, set 2 accessories

1921

1924

SECTION

1926

1931

GCRC Dwg. #1153, No description of monument, set 2 accessories
GCRC Dwg. #1153, No description of monument, section line shown, corner not shown.
GCRC Dwg. #1016, No description of monument, shown at intersection Maple & Dort Hwy., no witnesses or descriptions.
GCRC Dwg. #69, Iron stake 6" below
GCRC Dwg. #73, No description of monument, shown in centerline Maple & Dort Hwy.
MSHD RW Plans, No description of monument given, shown at intersection of Maple & Dort Hwy., Angle in NE quad: 90°25'(R), 1951 90°20'44"(M).
Certified Survey G. Bonno #32332, Fnd 1 ½" pipe, no witnesses given E–13, E–12, 2633.54' (R), 2633.53' (M). LCRC Rec. L.2415, P.179, G. Bonno #32332, Mon. box & bolt spike.
Certified survey L.2414, P.444, A. Vance Kupisch #13586, 1 1/4" Rod.

1990 1991

## Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998 Remon

Fnd 1-1/2" Steel Bar 10" below bit, +/-11' E. of CL Dort Hwy & 1.5' S. of CL Maple Ave. In 1815 Alex Holmes, D.S. set corner E-13 (gives no description of object) and shows 2 accessories (both are gone). He also gives measurements between corners E-13, F-13 40 chains; E-13, D-13 40 chains; E-13, E-12 40 chains. From 1920 thru 1960 Genesee County Road Commission did several projects along this section of Maple Avenue. No description of the object for corner E-13 is given, except in 1926 when it is called out as an iron stake. Several accessories are shown, none of which exist in 1998. In MDOT right-of-way plans, a distance from E-13, E-11 is shown as 5269.27 feet, also an angle in the NE quadrant of 90°25'. In 1998 I measure between these same corners E-13, E-11 5269.24 feet, with an angle in the NE quadrant of 90°20'44". In 1990 Gilbert Bonno, P.S. #32332 in a recorded LCRC Liber 2415, Page 179 shows four accessories, all of which are being found and check within ±0.10 feet. In 1991, Vance Kupisch, P.S. #13586 in a certified survey Liber 2414, Page 444 indicates three accessories, all of which are being found and check within ±0.10 feet. From 1987 thru 1998 the object in place for corner E-13 is described in several sizes  $1\frac{1}{2}$ " pipe, bolt spike,  $1-\frac{1}{4}$ " rod, and 2ft x 2in rod. Today in the 1998 Remonumentation Program I am finding a  $1\frac{1}{2}$ " steel bar 10" below surface in monument box  $\pm 11$ ' East of centerline of Dort Highway to the North and 1.5'South of centerline of Maple Avenue. I am also finding several of the accessories from the 1990 and 1991 surveys which check very close to record measurement. Based upon the distance measured by MDOT between E-13, E-11 of 5269.27 feet which checks within 0.03 feet of current measurement, the angle in the NE quadrant by MDOT of 90°25' as compared to a 1998 measured angle of 90°20'44" and the close comparison of the found accessories, I accept the position of the 1 1/2" steel bar as the best available evidence of the original corner.

C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner					
	S60W 77.275' Fnd MSHD tag in N. fc P.P. S60W 77.210' Fnd G. Bonno tag in E. fc P.P. N35W 82.615' Fnd MSHD tag in SW fc P.P. N35W 82.290' Fnd Bonno tag in S. fc P.P. N40F 74 190' Fnd "Survey Point" tag in NW fc P.P.	Ratified by Genesee County Peer Group September 30, 1998. I se the standard Bernsten Monument SS-A-5-BR-30 (3 1/4" D. bras- cap stamped "Genesee County Remonumentation Corner 32332 1998) with 30" x 2 3/8" O.D. Stainless Steel Tube with Plastic Base				

N40E 73.910' Fnd Bonno tag in W. fc P.P. N40E 73.800' Fnd MSHD tag in S. fc P.P. S45E 62.730' Fnd MSHD tag in NE fc P.P.

Surveyor's Michigan License No. 32332

S45E 62.265 Fnd Bonno tag in N. fc. P.P. Miller

Ratified by Peer Group in accordance with P.A. 345, 1990

Date 9/30/98

Co. Rep.