FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYURS, JAN. 28, 1971

RET 'ED MAY 14,1975

. IVISED JAN., 1983 R1498ED DCT., 1995

I, Kevin B. Cleaver, in a field survey on November 6, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	3
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25 11 31 31 32 33 34 35 36
 A. Description of original monument and accessories and/or subsequent restoration: 7-21-1821 General Land Office (GLO) fieldnotes: set post w/two accessories Undated Gould Engineering, Inc. (GEI) records: stake w/seven accessories Undated GEI records: T-iron w/four accessories 11-19-1965 recorded plat "Brisdale": dimensioned to section corner 5-16-1978 PA 132 Certified Survey, Liber 2009, Page 129: monument box w/three accessoriem 2-27-1979 Land Corner Recordation Certificate (LCRC), Liber 2034, Page 408: monument accessories 4-21-1989 LCRC, Liber 2369, Page 462: 1 1/4" iron in monument box w/three accessories 6-20-1998 GEI records: 1 1/4" iron in monument box w/four accessories 	ment box w/three C
B. Description of corner evidence found and/or method applied in restoring or reestablishing GLO corner and accessories not found Corner and accessories from both set of undated GEI records not found Confirmed within acceptable tolerance 1965 platted dimensions to section corner Recovered monument box and one accessory, and confirmed within acceptable tolera measurement from 1978 recorded survey Recovered monument box and two accessories from 1979 LCRC Recovered corner as identified and three accessories from 1989 LCRC Recovered corner as identified and four accessories from 1998 GEI records	nce the half-mile
The monument found was ratified by the Genesee County Remonumentation Peer Re November 4, 1998	
C. Description of monument for corner and accessories established to perpetuate locating the Set in concrete the standard Bernsten monument SS-A-5BR-30 with 3 1/4" brass cap s Remonumentation Corner, 1998, #29242" over 1 1/4" rod in monument box.	stamped "Genesee County Ratified by Peer Gro p in
N 60° W 97.11' set Genesee County Witness tag in southwest face power pole NORTH 12.06' north edge of concrete pavement N 65° E 115.91' set Genesee County Witness tag in northwest face power pole S 20° E 52.51' found nail/tag #32332 in west face power pole S 30° W 46.23' found chiseled notch west end 18 consequent	Co. Rep. Val. 2 m

PROFESSIONAL

SURVEYOR No.

29242

OFESSIO.

For corners in

Genesee County

3. Miscellaneous Property in Sec.

5. Private Claims

1. Public Land Survey 2. Property Controlling in Section

____, Recorded Plat

Kevin Banfield Cleaver, P.S.

Surveyor's Michigan License No. 29242

DGR/bb

98-GCRM-DGR-2806

Located In:

T<u>7N</u> R<u>7E</u>