MAR 23 2000

1999 KEMONOMEN LATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich PA 1970

SECTION For corners in

4

Lot No.

Genesee County				cated In	: Da	vison	Corner Code # G-4
1.	Public Land Survey		Т	7N	R	8E	G-4
			T		R.	····	•
		1.	T	•••	R		
			T		R		
2.	Property Controlling	S	T_{γ}		R		
	in Section	s	T		R		
3.	Miscellaneous	s	Т		R		
	Property in Section	s	Т		R		****

DEC 28 10 38 AM '99

GENESEE COUNTY REGISTER OF DEEDS

y 4358, P. 739

2

3

В

10

1:

Register of Deeds Stamp & File Numl

5.	Private Claim		
Dav f P.A	id J. Kenney, in a A. 74, Michigan P	field survey on November, 1999, do hereby state that under required. A. of 1970, the corner points mentioned in lines 1 and 2 above to	emen
onfo	rmance with regu	lations and rules therefore as required in the current manual of	SUIVE

Recorded Plat

Ι. Γ ts of in COL instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this

- Description of original monument and accessories and/or subsequent restoration:
 - 1822 G.L.O. Joseph Wampler D.S.
 - G.C.R.C. record book for Davison Township, Sheet 1, #4, Iron, 4 accessories 1929
 - L.C.R.C., L 1906, P. 400 by Ronald W. Keller 1975
 - Found monument box, 3 accessories 1979
 - L.C.R.C., L 2057, P. 400 by Myron L. Petrie, Found 1/2" rod in 1/2" pipe, 6" below conc. in monument box, 4 accessories
 - 1992 L.C.R.C., L 2481, P. 629, by Paul N. Brown, set P.K. and tag #20709 from previous survey monumentation due to re-surfacing of M-15, 4 accessories
 - Flint Surveying Section Corner Card, Found P.K. and brass tag, 4 accessories 1997
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - G-4 Section Corner, Section 9 & 10, T7N-R8E, Davison Township

Found P.K. nail with brass tag 1.4' west of centerline of M-15 and 31'+/- north of centerline of South Street, and 1 accessory from L.C.R.C., L1906, P. 400, (power pole S30°E, 62.50'), 2 accessories from L.C.R.C., L 2057, P. 961 (S20°W, 62.32' power pole, S40°E, 62.27 power pole and telephone pole); L.C.R.C., L 2481, P. 629, 1 accessory (S24°W, 62.83' set tag #20709 in NW face of power pole;) accessories (N20°E, 73.66, set nail and tag "KRC" in power pole, S85°E, 26.18', set nail and tag "KRC" in power pole, S23°W, 62.82', found nail and tag #20709 in power pole and S80°W, 26.27', found nail and tag "MSHD" in power pole).

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-4 Section Corner, Section 9,10, T7N-R8E, Davison Township

N20°E, 73.66', Found Nail and Tag "KRC" in power pole S85°E, 26.18', Found Nail and Tag "KRC" in npower pole S23°W, 62.82', Found Nail and Tag #20709 in power pole S80°W, 26.27', Found Nail and Tag "MSHD" in power pole

Ratified by Genesee County Peer Group November 17, 1999. I set t standard Bernstein monument (3 1/4" d. brass cap stamped "Genes County Remonumentation Corner, 1999" with 30" x 2 3/8" O. stainless steel tube over P.K. nail with brass tag.

National Park Signed by KENNEY Surveyor's Michigan License No. LAND HEVEYOF 39083 SELOHUT.

Date December 27, 1999

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYOR, JAN. 28, 1971 REVISED JAN., 1983

Ratified by Peer Group accordance with P.A. 345, 1990

Date ____