MAY 31 2000

## LAND CORNER RECORDATION CERTIFICATE LIBER 2518 PAGE 934

Filing Requirement of Act 74, Mich. P.A. 1970

CEC	11/200	
JEU	TION	

(Remonumentation corner under P.A. 345, Michigan P.A. of 1990)

+ (										3000	المحطف		***		2	
For corners in Genesee		Located	In:	,	Corner Code #	1					w		75 7 TR		5	
(County)  1. Public Land Survey	Al	W T 8N T T T T T T T T T T T T T T T T T	R 5E R R	5	K-3	Fu	41:		16AN	COLUMNY P.	30 74 33			Andre 70	-£	)
2. Property Controlling	S	т	R			1 to	rec			/		•	,			
in Section	S	T	R			.   "	awiata	5	Dage	la C4	4 WA B	0 E	Zila	Niver		i
3. Miscellaneous	S	T	R		•	.   "	egiste	OI	Deeu	ເຮ ວເ	amp	Ox F	-iie	Nun	Inei	
Property in Sec.	s	Т	R													
	Record	ed Plat					A	В	С	D E	F	G	Н	ı J	K	LN
E Privato Claima							1 -									

I, <u>Jack N. Owens, Prof. Surveyor</u>, in a field survey on <u>Aug. 5</u>, 19 <u>93</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

## NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Cor. to Secs. 1, 2, 11, & 12

Description of original monument and accessories and/or subsequent restoration: L2051, P665(1979); L2176, P73(1983) JSFokens, PS21567 Cert. Surv. L2276, P72(1986) - JNOwens; PS20709

1821,GLO-H.Ball,DS-Set post 1890,Co.Sur.Bk,P120-MMiddleton,CS

& 1906 DO -WRMiddleton,CS

Stone, 2 ft. long, lists 1 accessory 1920, GCRC-Mt. Morris Rd. Plans. Stone, 2 ft. long, no accessories.

1935, GCRC, Mt. Morris Rd. Plans. Iron rod, lists

6 accessories

1969/70,GCRC-Mt. Morris Rd. Plans. Fnd PK nail, lists 4 new accessories.

1969-1990, Rowe Engr.Survey Records (1969)DTRowe, PS11192 LCRC & Cert.Surv., L1864, P801 (1973); L2207, P655 (1984) DTRowe, PS11192

LCRC & Cert.Surv.L1988, P268 (1976) ; L2034, P371&382 (1979) ;

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993, Gen. Cor. Remon. Program Recovered 1/2" rerod in mon. box & 5 accessories. Recovered 1/2" rerod in mon. box & 5 accessories.

(Rerod dates to 1971. Hyd. & p.pole to NW=1976

Cert.Surv. & 1979 LCRC; p. pole to S. @ 30.15' =

1986 Cert.Surv.; p. pole to NE = 1990 Cert.Surv.)

Distance to J-3=2607.89' EDM (cf=2607.33' in 1970,

2631.25' in 1935, 2609.5' in 1920, 39.56' ch.

(2611.0') in 1890, 39.875 ch (2631.8') in 1821,

GLO, [39.375 ch. (2598.8') GLO corrected]). See J-3 LCRC

Distance to L-3=2643.75' EDM (cf=2644.10 in 1970, 2644.45' in 1935, 2643.4' in 1920).

Angle to  $S = 177^{\circ}36'28''$  (cf=177°37'23" in 1970,

177°35' in 1935, 177°36' in 1920).

I conclude the corner has long been perpetuated & doesn't seem to have changed since 1890, at least. It is probably a perpetuation of GLO corner by the County Surveyor.

This corner shows a pattern of recovery &

Description of monument for corner and accessories established to perpetuate locating the position of the corner: I set the standard Bernsten

Accessories: S05W, 30.15' Fnd nail/orange cap 16--4

N. fc. p. pole (1986 acc.) £ 30.49' £ set spike/GCRemon. tag E. fc. S25W, 47.31' Top cntr. fire hydr. (1976 acc.) N45W, 90.31' Fnd nail/tag 11192 S. fc.

p. pole (1976 acc.) £ 90.87' £ set spike/GCRemon. tag E. fc. N55W, 54.18' NE Cor. sq. rd. sign post N45E, 97.91' Fnd nail/orange cap 16--4

SE fc. p. pole (1990 acc.) & 98.36' & set spike/GCRem

m. tag NW fc.

Signed by Jack

starting in 1971 thru 1990. Lists 2 1969 accessories & 11 new accessories recovered 25 times over 21 year span.

Cert.Surv.L2390,P151(1990)-PNBrown,PS33134

Fnd p.k. nail 1969 & fnd 1/2" rerod in mon. box

2 3

4

5

6

7

8

9 10

11

12

13

18

19

30

17

-20

-29

32

-16

21

28

15

22

27

perpetuation by new monumentation by Co.Sur. & GCRC. Since the distances haven't changed in 70 to over 100 years, I conclude this reflects corners dating even back to the original GLO corners. I accept t I accept the 1/2" rerod in the mon. box in its present and long known location as a faithful and careful perpetuation of the position of the original corner.

Ratified by the Genesee Peer Group Dec. 1, 1993.





12

13

24

25

14

23

26

35

monument SS-A-5-BR-30 (3 1/4" d. brass cap stamped "Genesee County Remonumentation Corner

20709, 1993 "with 24" x 2 3/8" 0.D. stainless steel tube) over the 1/2" rerod in mon. box 3.0' N. of c/l pavement.

BIENIO JACK N. OWENS LAND SURVEYOR No. 20709 LARDS

Date Dec. 2, 1993

Surveyor's Michigan License No. 20709