

SURVEY & REMONUMENTATION COMMISSION
APR 07 1995

RECORDED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

2 47 PM '94

For corners in

GENESEE
 (County)

(REMONUMENTATION CORNER UNDER P.A. 345, MICHIGAN P.A. OF 1990)
 Located In: Corner Code -#

DEED LIBER 2528 PAGE 807

14747

9.00 Filed & Recd
 Register of Deeds Stamp & File Number

- 1. Public Land Survey T8N R 6E B-3
 T R
 T R
 T R
- 2. Property Controlling S T R
 in Section S T R
- 3. Miscellaneous S T R
 Property in Sec. S T R

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	15	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, RICARD H. KRAFT, in a field survey on NOVEMBER 18, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required, in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1822 GLO HORATIO BALL, SET POST
- 1878 WILLIAM B. SEARS, SET STONE. LIST 1 ACCESSORY
- 1954 GCRC - FOUND PIPE AND STAKE LIST 5 ACCESSORIES
- 1977 LCRC JAN FOLKENS. FOUND PIPE - RAISED WITH RAILROAD SPIKE. LIST 3 ACCESSORIES.
- 1993 CERTIFIED SURVEY. FOUND PIPE IN MONUMENT BOX. LIST 4 ACCESSORIES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1993 GENESEE COUNTY REMON. PROGRAM RECOVERED PIPE IN MONUMENT BOX 4 ACCESSORIES FORM 1993
- I CONCLUDE THAT THE CORNER HAS LONG BEEN PERPETUATED AND DOESN'T SEEM TO HAVE CHANGED. THE RECOVERED ACCESSORIES SHOW IT IS IN THE SAME POSITION. I ACCEPT IT AS A FAITHFUL AND CAREFUL RESTORATION OF THE POSITION OF THE ORIGINAL CORNER. APPROVED BY GENESEE COUNTY PEER REVIEW GROUP, DEC. 7, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- ACCESSORIES:
 N25°E, 75.77' - SET NAIL/G.C. REMON. TAG IN 30" MAPLE
 N45°E, 68.83' - FOUND MONUMENT
 S30°E, 26.31' - FOUND RE-ROD AT EDGE OF SHOULDER
 SOUTH, 60.98' - FOUND NAIL AND TAG IN 10" THORNAPPLE
- I SET THE STANDARD BERNSTEN MONUMENT (3 1/4" D. BRASS CAP STAMPED "GENESEE COUNTY REMONUMENTATION CORNER, 1993" WITH 2 3/8" O.D. STAINLESS STEEL TUBE) OVER PIPE IN MONUMENT BOX.

Signed by Richard H. Kraft
 Surveyor's Michigan License No. 10064

Date Nov. 19, 1993

