SUNVET & REMONUMENTATION

4. PED 22 CHARLE

n.	tified by Peer Group In		•••				
Ha ac	tified by Poer Group In cordance with P.A. 1/15, 1990		neen				•
	Rep. Callal	COMMISSION	LIBER	2601	PAGE S	32	
Da		1995 Remonumentation Prog - LAND CORNER RECORDATION CERT	ram NFI CATE	19 G	T.	7	EN
For	corners in	Filing Requirement of Act 74, Mich. P		13.55	=======================================	REC:	RECORDS
		cated In: Corner Code ##		m m Su	\sim) ROS
	(County)	Saled III.		, c 0			3
1.		8N R 6E B-5			10 PH		
	· T	R		٠.,	SS		
2.		R				*	~ 0° "
3		R			2354		
J.		R	Regis	ter of Deeds	Stamp &	File Num	ber V
4.	Lot No, Recorded Plat			A B C D	E F G	ніј	KLM
5.	Private Claims			2 6 5	III		
	,			3		+ + +	
		rvey on <u>September 15</u> , 19 <u>95</u>		5		-1011	12-
		A. 74, Michigan P.A. of 1970, the corner points mention with regulations and rules therefore as required in	in the	6 18 17		_1514	
		United States Department of the Interior, Bureau of and/or that the corner points mentioned in lines 3, 4	Lanu	8 19 20		-2223	34
Cou	art of Law; established, re-established,	he Michigan Board of Land Surveyors or by a Decre monumented, re-monumented, recovered, four		9	- 	1-1-1	11
	ressed below:	the same town and range, may be recorded		30 29	-28-	27-26	25
.,,	on this certificate.	the same term and renge, may be recorded		12 31-32	-33	-3435	36
A.		d accessories and/or subsequent restoration	n:	13 hh.			
		vith two (2) accessories d course descriptions Project No. 8165, C-	-9				
		e with six (6) accessories	•				
	October 30, 1962 Recorded	plat of "Stanley Acres" plat monuments					
	October 26, 1966 Recorded 1973 Certified s	plat of "Labian Meadows" plat monuments survey, Liber 1845, Page 905, re-rod in mo	ts onument bo	ox with four	(4) access	sories	
	1979 Certified s 1973 surv	survey, Liber 2051, Page 658, re-rod in mo	onument bo	x and three	(3) acces	sories fr	om
В.		d and/or method applied in restoring or reest	tablishina ca	ornar:			
.	begonprior of corner evidence regin	s and/or motified applied in restoring or reest	tablishing ce	orner.			
	Found 1/2" re-rod in monument bo	ox, 1.0'± north of center line of asphalt.					
	The recent measure closely repre- linear and angular measurements	sents the GLO measurements, the current A-5 to B-5 and B-5 to C-5 closely represer	ents				
	the 1915 GCRC route; this monument fits the recorded plats of "Stanley Acres" 1962, and "Labian Meadows" 1966; monument also fits the description according to the certified						
surveys of 1973 and 1979. We also found two (2) of the 1973 and 1979 surveys							
	(PK nail/washer in power pole nor recorded 32,29').	th recorded 51.30' and PK nail/washer in fe	ence post				÷
	The monument found was ratified	by the Genesee County Peer Review Com	nmittee				•
	on November 1, 1995, as the acce						
C.	Description of monument for corner	and accessories established to perpetuate lo	ocating the p	position of th	e corner:		
		•					
	Set the standard Berntsen monum	ent SS-A-5-BR-30 with 3 1/4" brass cap st	tamped Ge	nesee Coun	ity Re-mo	numenta	tion
	Corner 1995, #29242 in concrete	over a 1/2" re-rod in monument box, 1.0'±	north of ce	nter line of a	ısphalt.		
	South, 58.34' - Set 36 N 45° E, 52.88' - Set 36	Od nail/re-monumentation tag in east face of nail/re-monumentation tag in northwest	of transform	ner pole			
	S 40° E, 41.44' - Set cl	niseled 'X' in south end of 12" CMR	, , , , , , , , , , , , , , , , , , ,	1166			
		The ist named in South lace of power pole	Section 1				•
		1 0/1 Harring	77-0		ر ــــــر.	_	
Sig	ned by Form Ban	By: Kevin Banfield Leaver, 19.5.	<u>Jor</u>	1 7	1996	<u>フ</u> 	·
Sur	veyor's Michigan License No2924	2 Its Field Manager 2001	FORM APPROVED	BY MICHIGAN STAT	E BOARD OF LANG	D SURVEYORS, . REVISED	JAN. 28, 1971 MAY 14, 1975
		The state of the s			•		ED JAN., 1983
	•	And the second second	James T.				