LAND CORNER RECORDATION CERTIFICATE


Filing Requirement of Act 74, Mich. P.A. 19702 115 111 GRMONUMENTATION CORNER UNDER P.A. 345, MICHIGAN P.A. OF 1990)

| For corners in County Control | NUMENTATION CORNER L Located In: | Ormer Code // | DEED 2528 PAGE 801 |
|---|---------------------------------------|---------------|--|
| 1. Public Land Survey | T <u>9N</u> R <u>6E</u> T R T R | E-3 | 14741 |
| Property Controlling in Section Miscellaneous | S T R S T R | | 9.00 Filed & Resd Register of Deeds Stamp & File Number |
| 3. Miscellaneous Property in Sec. 4. Lot No | S T Recorded Plat | | A B C D E F G H I J K L |

I. RICHARD H. KRAFT , in a field survey on NOVEMBER 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in tines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumenter recovered, found as

4 Lot No. .. 5. Private Claims ____

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
 - 1822 GLO HORATIO BALL, SET POST
 - G.C.R.C. LAKE ROAD PLANS, FOUND IRON STAKE IN MON. BOX. LIST 4 ACCESSORIES 1972 N.C. JONES, SURVEYOR, FOUND T IRON IN MON. BOX, LIST 3 ACCESSORIES, 1 FROM G.C.R.C.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1993 GENESEE COUNTY REMON. PROGRAM RECOVERED T IRON-IN MON. BOX AND 1 ACCESSORY T IRON WAS FOUND IN 1972 850°E 26" OAK, 54.0"

I CONCLUDE THAT THE CORNER HAS LONG BEEN PERPETUATED AND DOESN'T SEEM TO HAVE CHANGED SINCE G.C.R.C. REPAVING. THE TWO RECOVERED ACCESSORIES PREDATE 1972 SHOWING IT IS THE SAME POSITION. I ACCEPT IT AS A FAITHFUL AND CAREFUL RESTORATION OF THE ORIGINAL CORNER.

APPROVED BY GENESEE COUNTY PEER REVIEW GROUP. DECEMBER 1, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

SET NAIL/ G.C. REMON. TAG, 10" ASH. ACCESSORIES:

NGO°W 49.12' SET NAIL/ G.C. REMON. TAG, 10" ASR. S45°E 62.90' SET NAIL/ G.C. REMON. TAG, 10" OAK S60°E 54.00' SET NAIL/ G.C. REMON. TAG, 28" OAK

I SET THE STANDARD BERNSTEN MONUMENT (3 1/4" D. BRASS CAP STAMPED "GENESEE COUNTY REMONUMENTATION CORNER, 1993" WITH 30" X 2 3/8" O.D. STAINLESS STEEL TUBE) OVER T IRON IN MON. BOX

Surveyor's Michigan License No.

Date DECEMBER 28, 1993

1741, 25, MAL, ERDYSVRUZ CMAJ VO DRAGE STATE MADI