,			The Contract of the Contract o								
	<i>~</i> 1	IFY ENTA	, l AND CORN	ED BEGARDATIO	LI OFRT-FIGAT	- 5770				1	
	(c)	IN WALL	LAND CORN	ER RECORDATIO	N CERTIFICATI	E	• • •	, १९५५ है।	ก. : ก. :		1 - 2 2
For	corners in REMO	CONNIL	Filing Requi	rement of Act 74, t UNDER P.A. 3 Corner Code	Mich. P.A. 1970 45, MICHIGAN	$\mathbf{P} \cdot \mathbf{A} = 0$	F 1990))			
GE	NESEE \-	"by ri	cated in:	Corner Code	z##	0 E A .	1	2921 5623	}		
	(CO(n)(A)	Hy andle	20.	•	DFF	ክ ጨሥ /	0.0	1 (4) (1) L		. ر	
	Public Land Survey	COMILL	T 9N R 7E	C-3	ĽĺBĚ	R 25	Z3 PAG	E	313)	
••	Tobilo Edilo Odiroy	O-	T R	, ber 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		•					
			T R			4755			*		
			T R							•	
2.	Property Controlling		T R			A 1				٠, ,	
	in Section		T R		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Filed	a re	d			:
3.	Miscellaneous	S	T R			egister of			File I	dmuk	er
	Property in Sec.	S	T R		<u> </u>						···
					-						
	Lot No					А В	C D E	F G	H 1	1 ,1	K L I
5.	Private Claims				·	- , [
					•	, , ,		-1-	-i-	_i-	Ti
	•								1	\sqcap	
. 15	70114DD 11 11D4D1	T	MOLTE	ADED 17	. 00	* - · ?·	- -	-9-	-101	11 	1-12-
I. K	ICHARD H. KRAFT ereby certily that under	°			_		1-1-				
in li	nes I and 2 above wer	6 18		-16	-15	1 '4	 				
curr	ent manual of survey in	7			_						
Man	agement or by a decree	8 - 19	20	-21-	22	23					
Cou	ve were in conformance	9			┵	 -	╁╌╁╌				
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							29	_28	-27	26-	25
NO	TE: Not more than	11					1-1-				
	on this certifica	12 _31		_33	_34	35-	36-				
				·		13					<u> </u>
A.	Description of origin	nal monument a	ind accessories a	nd/or subsequent re	estoration:		•				
	4										
	1822 GLO HORA	TTO BALL. I	L.S., SET POS	Т							
				LIST 2 ACCESS	ORIES						
				T 4 ACCESSORII							
			E,LIST 4 ACCE						•		
				5 ACCESSORIES							
				WN, LIST 3 ACC	CESSORIES						

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1993 GENESEE COUNTY REMON. PROGRAM RECOVERED T IRON IN MON. BOX & 2 ACCESSORIES SW 44.26', NE BOLT-SUNOCO SIGN \$30°E 50.33', 15" MAPLE

I CONCLUDE THAT THE CORNER HAS LONG BEEN PERPETUATED AND DOESN'T SEEM TO HAVE CHANGED SINCE G.C.R.C. REPAVING. ACCEPT IT AS A FAITHFUL AND CAREFUL RESTORATION OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED BY GENESEE COUNTY PEER REVIEW GROUP. NOVEMBER, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

AC	C	Ę	S	S	0	R	Ι	E	5	:	
						_		_			

SET NAIL/G.C. REMON. TAG IN 8" N30°W 68.951 MAPLE

S45°W 44.301 NE BOLT IN SUNOCO SIGN

N45°E 56.33 WESTERLY POLE OF CHURCH SIGN

\$45°E 49.55' NORTHWEST CORNER OF TELEPHONE PEDESTAL.

I SET THE STANDARD BERNSTEN MONUMENT (3 1/4" D. BRASS CAP STAMPED "GENESEE COUNTY REMONUMENTATION CORNER, 1993" WITH 2 3/8" O.D. STAINLESS STEEL TUBE) OVER T IRON IN MON. BOX.



Surveyor's Michigan License No.

ID SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975