RECORDED

O_{MO}	•	- O.E.	LAND CORNER RECORDA	ATION CERTIFICATE	::
•	07	1995	Filing Requirement of Ac	+ 74. Mich. P.A. 1970	,

For corners in	AP (REMONUMENTALYON	CORNER	UNDER	P.A. 345,	MICHIG
GENESEE	AP (REMONUMENTALIZON Located In	:	Co	rner Code =##	10

T 9N R 7E 1. Public Land Survey

DEED 2528 PAGE 814 14754


2. Property Controlling _ T _ in Section Τ. S. Miscellaneous Property in Sec.

9.00 Filed Recd Register of Deeds Stamp & File Number

 $_$, Recorded Plat $_$ Lot No. 5. Private Claims ___.

, 19 __93 i, RTCHARD H. KRAFT , in a field survey on NOVEMBER 17 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1822 GLO HORATIO BALL, SET POST

M.B. STAGE, C.S., SET STAKE, NO ACCESSORIES

G.C.R.C. FOUND STONE, SET IRON PIN; LIST 4 ACCESSORIES 1972 L.C.R.C. SHELDON BROWN, FOUND 1/2" PIPE IN MON. BOX, LIST 3 WITNESSES.

1992 CERT. SUR. PAUL BROWN, FOUND PIPE IN MON. BOX, LIST 4 ACCESSORIES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

GENESEE COUNTY REMON. PROGRAM 1993 RECOVERED 1/2" PIPE IN MON. BOX & 2 ACCESSORIES S5°W 47.44' F - N & T IN P.P. NORTH 32.90' F - N & T IN P.P.

I CONCLUDE THAT THE CORNER HAS LONG BEEN PERPETUATED AND DOESN'T SEEM TO HAVE CHANGED SINCE 1972, AT LEAST. I ACCEPT IT AS A FAITHFUL AND CAREFUL RESTORATION OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED BY GENESEE COUNTY PEER REVIEW GROUP. NOVEMBER, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ACCESSORIES:

SET NAIL/ G.C. REMON. TAG IN 10" N45°E 43.70' STUMP

SET NAIL/ G.C. REMON. TAG IN .

ANCHOR POST FOUND NAIL & TAG IN POWER POLE

32.90 NORTH FOUND NAIL & TAG IN POWER POLE 47.44

I SET THE STANDARD BERNSTEN MONUMENT (3 1/4" D. BRASS CAP STAMPED "GENESEE COUNTY REMONUMENTATION CORNER, 1993" WITH 2 3/8" O.D. STAINLESS STEEL TUBE) OVER 1/2" PIPE IN MON. BOX.



Surveyor's Michigan License No.

SOUTH 32.63'

STATE BOARD OF LAND SURVEYORS, JA REVISED MAY 14, 1975 REVISED JAN., 1983