Gladwin County Remonumentation

G 12

PAGE 36

REMONUMENT	LAND CORNER RECORDATION CERTIFICATE
ACIVIO	Filing Requirement of Act 74, Mich. P.A. 1970

APR 07 1995 For corners in COMMISSISPRETED IN: Gladwin

Public Land Survey

Corner Code ##

STATE OF MICHIGAN GLADWIN COUNTY RECORDED

28 DEC 94 2:56 P.H.

BONNIE K. HOUSE REGISTER OF DEEDS

R **Property Controlling** т R in Section Miscellaneous . T . R . Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No ,	Recorded Plat		
5.	Private Claims			

T 17N R 1E

. in a field survey on ___September 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: Recorded Plats - American Sportsmen and Hunting Dog Owner Association Sub. - L.2, P. 26 - 1942, Wilson Point Sub.; Forest View Sub.; Keenes Pleasure Island Sub.; Twin Oaks Sub. Unrecorded Surveys - Wade-Trim - #3150 - 1965 and 6039 - 1969.

10

11

12 13

G 12 Set 1/2 mile post - H. Parke - 1832.

Pine 30" N 39° E 16 Lks. Birch 13" S 52° W 15 Lks.

Dundas Notes - Found - Pre 1957. LCRC - P. 47 - Found 1-1/2" pipe - Lapham - 1972. Recorded Surveys - L. 1, P. 90 - 1972; L. 1, P. 821 - Found 3/4" pipe - 1978.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G 12 Found 3/4" I.D. pipe of record LCRC and survey 33.41' E. of found concrete monument in American Sportsmen Sub. -Excavate - Found 3/4" I.D. x 3.5' long pipe - Found 3/4" x 0.9' iron pipe on N. side of pipe, down 0.8' - found old wood stake 1.5" x 1.5" x 1' with nall along side 0.3' + W. of found pipes, down 0.8'. Accept base of wood stake point as true corner position based on agreement with found concrete monument to W. Wood stake monument accepted as the best available evidence of position of original corner.

P.A.345 of 1990 Gladwin County

APPROVED LAND CORNER

Co. Rep

Date .

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G 12 Replace wood stake, pipes and nall with 2-1/2" Gladwin County aluminum cap on 5/8" x 36" rebar with 4" plastic drain tile sleeve with concrete - down 0.5'.

N 86° W 33.03' (33' -P) to concrete monument.

S 56° W 41.49' to concrete monument.

S 20° E 53.88' to nail and tag in W. side 12" Maple.

S 58° E 63.25' (63.02' -R) to set nail and tag in S. side U.P.

N 65° E 41.85' to nail and tag in S. side 16" Pine

N 46° W 43.20' to nail and tag in SW. side 6" Maple.

Surveyor's Michigan License No.

SURVEYOR No. 39088 POFESSIONA

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. **REVISED MAY 14, 1975**

OF MICHIGAN

CRAIG W.

McVEAN

PROFESSIONAL