SURVEY & TATIO

Gladwin County Remonumentation

PAGE 31

APR OF	7 199	33	LAND		IER RE					ATE
KLIE	01 C	SION	Filing	Requi	rement	of Act	74, N	Aich. F	2.A. 1	1970

Fo	r corners in	OWWISSIO - Filling head.	estimated Act 74, mich. P.A.	1970
	Gladwin (County)	Located In:	Corner Code ##	
1.	Public Land Survey	T <u>17N</u> R <u>1W</u> T R T R		STATE OF HICHIGAN GLADWIN COUNTY RECORDED
2.	Property Controlling in Section	S T R S T R		28 DEC 94 2:55 P.M.
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Decis Stamp of File Number
4.	Lot No , f	Recorded Plat		
	Private Claims	The state of the s		
				3
				4 - 7 8 9 10 11
Ma abo	rrent manual of survey instr nagement or by a decree of ove were in conformance wi	ructions of the United States Dep a Court of Law and/or that the cor ith the rules of the Michigan Board	and rules therefore as required in the artment of the Interior, Bureau of Lamer points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree ce-monumented, recovered, found	nd 7 15 8 19 20 21 22 23 14 as 10 30 29 28 27 26
NC	OTE: Not more than 4 of on this certificate	corners, all in the same town.	and range, may be recorded	11 12 31 32 33 34 35
A.	Description of original	monument and accessories a	and/or subsequent restoration:	·
	<u>L 9</u> GLO resurvey - old Hemlock 14" S 61° W 25 Beech 12" N 4° E 24 Lks.		1852.	APPROVED LAND CORNER P.A. 345 of 1990 Gladwin County
	also in line with fence No LCRC - P 113 - Found bo Recorded Survey - L. 2, i	spike in line between Section corn orth and South - Pre 1957. oat spike - Lapham - 1975. P. 409 - 1989 - Wade-Trim, Inc. pham and Associates Job # G-9	Co Da	Rep. M. Menen- 12-2-94
В.	Description of corner	evidence found and/or method	d applied in restoring or reestab	lishing corner:
	<u>L 9</u> Found 3/4" boat	spike per LCRC, recorded surv	rey, and	

Dundas notes at physical centerline East-West road and North-South fence line. Monument accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>L 9</u> Replace boat spike with 2-1/2 Gladwin County aluminum cap on 5/8" x 36" rebar with 4" plastic drain tile sleeve with concrete down 0.5' N 20° W 19.97' to pk and tag in E. end 12" CMP.

N 60° W 86.29' to nail and tag in NE. side double 4" Ash. S 46° W (S 45° 10' W. - Dundas) 95.22' (95.37' - Dundas) to set nail and tag in NW. side 48" (14" Dundas) Oak. S 5° W 49.31' to nail and tag in W. side 8" Oak.



Signed by Cracy	M.	Me	Ven
Suprovor's Michigan Licen	se No	390	88