SUFFYEY &

JAN 1 7 19 AND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 100

For corners in		equirement of Act 74, Mich. P.	A. 1970			
GLADWIN (County)	COMMISSION Located In:	Corner Code #		STATE OF MICHIG	Υ	
1. Public Land Survey	T <u>17N</u> R <u>2W</u> TR TR	E-12		FILED-RENONUMENT		
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		Book	BONNIE K. HOUS REGISTER OF DEE	EDS	
			Regis	ster of Deeds Stamp &	File Number	
4. Lot No, Reco 5. Private Claims	rded Plat					
O. I IIVale Ciailis			1 A B	CDEFGH	I J K L	
conformance with regulations and United States Department of the hat the corner points mentioned Board of Land Surveyors or by	Interior, Bureau of Land Manage in Interior, Bureau of Land Manage in In lines 3, 4 and 5 above were in	MBER, 19 95 do hereby state that us s mentioned in lines 1 and 2 above wer current manual of survey instructions of nent or by a decree of a Court of Law and conformance with the rules of the Michi established, re-established, monument	the 5	8 9 10 17 16 15	2 - 1 - 12 - 14 - 13 -	
ecovered, found as expressed be	slow:	established, re-established, monument	led, 8 —19—	20 31 33		
NOTE: Not more than 2 com on this certificate.	ners, all in the same town and n	ange, may be recorded	9 10 30		23 -24-	
		,	11	29 - 28 - 27 -	26 25-	
			12 31	32 33 34	_3536	
Description of original mon 1830 WILLIAM A. BURT SET 1/4 POST WIT(1)MAPLE 8" S69° (2)HEMLOCK N84°W	nument and accessories and/	Or subsequent restoration: 1974 LAPHAM L.C.R.C. #78 WITSAME AS (3), (4) & (5) 1991 LAPHAM UNRECORDED L.C.	13			
1974 LAPHAM SURVEY A SET CAPPED IRON MIDWA CORNER, IN CENTERLINE WIT(3)N30°E 69.13° 6° (4)S60°E 35.92° CO (5)S65°W 30.27° CO	WORKING DWG. AY BETWEEN SW-NW OF COUNTY ROAD "MAPLE OR FENCE POST	COUNTY ROAD CONSTRUCTION, FOUND 3/4" CAPPED IRON IN C OF ROAD WIT(6)NB5W 12" ASH 82.05' (7)S10"W GUIDE POST 157.5 (8)S20"E POWER POLE 106, (9)S45"E 6" POPLAR 88.50"	ENTERLINE			
Description of corner evide	ence found and/or method en	plied in restoring or reestablishing o				
FOUND 3/4" # CAD DO	ENT, BOTTOM OK, EXCAVATE	NO OTHER CORNER FOUND, IN CE MONUMENT IN PLACE OF FOUND		PAUL B. LAPHAM PROFESSIONAL SURVEYOR	I U N	
This Corner establishe	ed in Gladwin County Rer	monumentation Program.		No. 9433		
See dossier for detail	•			FESSION		
Description of monument for	r corner and accessories esta	blished to perpetuate locating the p	osition of the co	orner:	, .	
L-12: CORNER COMMON	TO SECTIONS TO A. TH	ION CAP, MARKED P.S. #9433.				
WITNESSES: N85°W 82.10' NAIL & TAG IN 12" ASH S10°W 158.05' NAIL & TAG IN GUIDE POST S20°E 106.00' POWER POLE S40°E 46.70' NAIL & TAG IN POPLAR			APP	APPROVED LAND CORNER P.A. 345 of 1990 Gladwin County . Rep.		
			Date 12	118/95	·	
ned by faul 1	1. Japan	.	22	province of the second		
eyor's Michigan License No.	4433	Date	2-22-91			