REMONUMENTATION

SEP 07 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE LIBER 001 PAGE 273

Filing Requirement of Act 74, Mich. P.A. 1970 Gladwin County Remonumentation

STATE OF MICHIGAN

GLADWIN COUNTY

Filed-Rémon

16 AUG 1999 2:36:20 PM

RONNIE K. HOUSE REGISTER OF DEEDS

For Corners in GLADWIN Located In: Corner Code#: (County) 1. Public Land Survey T. 17N R. 2W 2. Public Controlling in Section R 3. Miscellancous T. Property in Section Recorded Plat 4. Lot No. 5. Private Claims

Register of Deeds Stamp & File Number

1. Mark R. Robison, in a field survey on March 26, 1999, do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1850 William A. Burt Set Post 10, 11, 14 & 15 Wit-(1)Beech S56E 13 (2)Synn 12 NI 1/2W 13

1963 Edmands Eng. Plat of Woodby's Waters Edge & Misc. working dwgs

1965 Lapham survey Wit-none

1979 Lapham LCRC#240 Found 1/4" rerod Wit-(3) East Fe. Cor. 40.65 (4)N40E 20" Elm 33.15 (5) Plat: Woodby's Waters Edge

1980 Lapham survey, Wit-same as (3), (4) & (5)

1982 Lapham LCRC#278 Fd 1/4" rod, raised with 1/2" rod Wit-(6)S15E 2" x 5' Pipe 25.60 (7)N45E Power Pole 79.50 (8)N45W Road Sign 32.72

1987-98 Lapham working dwgs

1998 Lapham survey Found 3/8" Iron Wit-(8)East, 40.8' - Conc. Mon. (9) South, 31.65' - Conc. Mon. (10)N45E, 33.15' - 30" Elm (11)S40W, 66.55' - 6" Elm

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: APPROVED LAND CORNER

Found 1/2" x 18" rerod opposite fence to East, in centerline of road extended to West and Southwest. Corner agrees with plat of Woodby's Waters Edge Subdivision. Also agrees with witnesses (3), (8) &(9). Set 5/8" x 36" rerod in place of found 1/2" x 18" rerod.

See dossier for detailed report.

P.A/345 of 1990 Gradwin County

Co. Rep

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-5; Set 5/8" x 36" rerod with Gladwin County Remonumentation cap marked P.S.#27458.

Witnesses:

East, Concrete Monument, 40.80' South, Concrete Monument, 31.63' S45°E 3' x 5' Stone "x" in SW Cor. 81.50' \$50°W 4" W. Pine, nail & tag, 83.68' N25°W 4" Ash, nail & tag, 89.22'

Surveyor's Michigan License No. 27458

MARK R. ROBISON PROFESSIONAL SURVEYOR No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT.,