SURVEY & REMONUMENTATION

DEC 0 1 1999

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970 Gladwin County Remonumentation

LIBER 001 PAGE 289

For Corners in GLADWIN (County)	Located In:	Corner Code#:	
1. Public Land Survey	T. <u>17N</u> R. <u>02W</u> T R		STATE OF HICHIGAN GLADWIN COUNTY FILED-RENOMIMENTATION
2. Public Controlling in Section3. Miscellaneous Property in Section4. Lot No.	S T R S T R S T R S T R , Recorded Plat		19 NOV 1999 2:05:44 PM BONNIE K. HOUSE REGISTER OF DEEDS Register of Deeds Stamp & File Number
5. Private Claims	A	Landa and Grahat and an	ARCDEFGHIIKLM
were in conformance with reguinstructions of the United State decree of a Court of Law and/o conformance with the rules of t	urvey on April 1998, do gan P.A. of 1970, the corner points me lations and rules therefore as required is Department of the Interior, Bureau of r that the corner points mentioned in life Michigan Board of Land Surveyors d, monumented, re-monumented, recov	in the current manual of survey I Land Management or by a nes 3, 4 and 5 above were in or by a Decree of a Court of	2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 5 4 15 14 13

A. Description of original monument and accessories and/or subsequent

NOTE: Not more than 2 corners, all in the same town and range, may be

restoration: 1856 Geo H. Cannon

recorded on this certificate.

1938 MSHD road plans & field notes Axle with Gear Boat Spike on centerline

Wit-(3)N42W 61,40 to Tel Pole (4)S55W 56.05 to BM in 14" Poplar (5)S55E 55.70 to Tel Pole

1960+/- Edmands Eng. work dwgs Wit-same as (3), (4) & (5)

1974 Lapham LCRC#99 Fd 2" Bar in Mon Box Wit-(6)N65W 70.75 P.P.

(7)S50W 60.70 C/L Top Conc R/W Marker (8)N50E 106.82 15" Cottonwood

10 30

31

29

28 27

1982 Fluharty LCRC#277 Fd 1 1/2" Iron in Mon Box Wit-(9)12" Willow S35E 148.00 (10)18" Poplar N50E 106.37 (11)NE Cor Conc R/W Marker

S60W 60.70

1983-86 Lapham 6 surveys & work dwgs Wit-same as (6), (7) & (8)

26

1998 MDOT Found 1 1/2" Iron Rod in Mon Box See MDOT Plans#26011 for Loc & Wits

Gladwin County

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence found and/or method applied in restoring or re-establishing corner evidence for the corner e A:\345 of 1990

Found 1 1/2" Iron in Monument Box at intersection M-18 and county road East-West. Iron agrees with witnesses (8), (9) & (10) and MDOT 1998 witnesses. Also agrees with 1938 MSHD, 1970 Lapham and 1998 MDOT measurement to North (K-12, T18N, R2W)

See dossier for detailed report.

West, P.K. Nail, Centerline 81.34

Date C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-1: Corner common to Sections 35 & 36, T18N, R2W, and Sections 1 & 2, T17N, R2W, on township line. Set 5/8" x 18" rerod in Monument Box with Gladwin County Remonumentation cap marked P.S.#27458.

\$30°E 24" Willow, nail & tag, 147.80' (MDOT) \$50°E 4" x 4" Post, nail & ribbon, 62.20' (MDOT) N65°E 4" x 4" Post, nail & ribbon, 66.68' (MDOT) N50°E 24" Cottonwood, nail & tag, 106.10' (MDOT) N45°E 1/2" x 18" Rerod 92.37 East, P.K. Nail, Centerline 80.57

ROBISON

ROFESSIONAL

SURVEYOR

No.