SURVEY & PENONUMENTATION

JAN 17 1996

Surveyor's Michigan License No.__

LIBER 001 PAGE 96

COMM	ISSION PINE	g Requirement of Act 74, Mich	ERTIFICATE	
For corners in	• 1491	g requirement of Act 74, Mich	STATE OF MICHIGAN	
GLADWIN	Located In:	Corner Code #	GLADVIN COUNTY	
(County)	Located III.	Comer Code #	FILED-RENONUMENTATION	
1. Public Land Survey	T 17NR	T_17NR 2W K-6 26 DEC 95 10:56 A.H.		
anno Lanta Gartoy	Ť <u> </u>			
	ŢR_		BONNIE K. HOUSE	
2. Property Controlling	TR S T R		REGISTER OF DEEDS	
in Section	S TR_			
3. Miscellaneous Property in Sec.	S TR_ S T R			
Froperty in Sec.	S I		Register of Deeds Stamp & File Num	nbei
4 Latha Bassa	ad al Disa			
4. Lot No, Recor 5. Private Claims	ded Plat		A B C D E F G H I J K	L
			2 6 5 4 3 2	Ţ
		MAY-	3	
I, PAUL B. LAPHAM	, in a field survey on !	NOVEMBER , 19 95 do hereby state t	that under 4 - 7 - 8 - 9 - 10 - 11	 —12
requirements of P.A. 74, Michiga	in P.A. of 1970, the come	er points mentioned in lines 1 and 2 aboved in the current manual of survey instruction	/e were in	Ī
United States Department of the I	nterior, Bureau of Land Ma	anagement or by a decree of a Court of La	swand/or of 10 12 12 15	 —13
that the corner points mentioned Board of Land Surveyors or by	Michigan 7 1 1 1 1 1	$\bar{\perp}$		
recovered, found as expressed be	low:	,	8 -19 -20 -21 -22 -23	 24-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9	_
on this certificate.		•	10 30 29 28 27 26	2 5-
			11	\pm
			12 31 32 33 34 35	-36
A. Description of original mor	nument and accessorie	es and/or subsequent restoration:	13	
1830 WILLIAM A. BURT WIT(1)POST 8" ELM N13°W 10		1970 PAUL LAPHAM SURVE	Y	
(2)ÉLM 10" S19E 6	3	1986 PAUL LAPHAM SURVEY	Y & WORK SHEET	
1971 PAUL LAPHAM L.C. SET 1/2" BAR, MIDWAY	.R.C. #25	1991 PAUL LAPHAN UNRECTORUNTY ROAD CONSTRUCTION	ORDED WIT, FOR	
WITH N.E. & S.E. CORNE WIT(3)S45°W 49,45' P.	ER	WIT(6)N30W 16" BOX EL (7)N80°E P.P. 31.55'	DER 91.25°	
(4)S85°E 31.15' CC (5)N54°W N. END 3	OR. POST	(8)S40W POWER POLE	. 83.40°	
1971 PAUL LAPHAM	70 C.M.F. 30.00	(9)N45W CENTER TOP	36" C.M.P. 29.93"	
WITNESS CARD- WITNESS				
Description of corner evid	ence found and/or met	thod applied in restoring or reestablis		
FOUND P.K. NAIL 1.8 WE NO. (6), (7) & (8), 0.5 GLADWIN MON. IN POSITI	NUCLINI OF EXISTING	ASPHALT ROAD, RESET CORNER F. P.K. NAIL, EXCAVATED NO CORNER	S FOUND, SET	
			LAPHAM PROFESSIONAL SURVEYOR No.	
This Corner established	ed in Gladwin Coun	ty Remonumentation Program.	No. 9433	
See dossier for detai		•	FESSION	
. Description of monument for	or corner and accessor	ries established to perpetuate locatin	a the position of the corner	
K-6: CORNER COMMON	TO SECTIONS 13 & 1		j	
WITNESSES:				
N30°W 91.25' - N	NAIL & TAG IN 16" BO NAIL & TAG IN POWER	OX ELDER	APPROVED LAND CORNER P.A. 345 of 1990	
S40"W 83.40" — N N65"W 96.20" — (NAIL & TAG IN POWER CONC. COR. OF GARAG	POLÉ	Gladwin County	
NORTH P.K. NAIL EAST P.K. NAIL 2,	2.0'	-	Co. Flep. Land Mongan	