## SURVEY & REMONUMENTATION

DEC 0 1 1999

SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 001 PAGE 278 **Gladwin County Remonumentation** 

6

7

19

٠į٠ 30

3

4

6 - 18

8

Q

11 -31

For Corners in GLADWIN			STATE OF MICHIGAN
(County)	Located In:	Corner Code#:	GLADWIN COUNTY FILED-REMONUMENTATION
1. Public Land Survey	T. <u>18N</u> R. <u>02W</u> T R	<u>K-6</u>	19 NOV 1999 2:03:22 PM
2. Public Controlling in Section	S T R S T R		BONNIE K. HOUSE REGISTER OF DEEDS
3. Miscellaneous Property in Section	S T R S T R		n
4. Lot No 5. Private Claims	, Recorded Plat	·	Register of Deeds Stamp & File Number

1998, do hereby certify that under I. Mark R. Robison, in a field survey on April requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1856 Geo H. Cannon Set 1/4 Section Post Wit-(1)W. Birch N50W 25 (2)Cedar 5 N85E 6

1939 MSHD Axle Shaft Wit-(3)N37W 72.60 Tel. Pole (4)N63E 57.10 Fe Cor Post (5)S69E 54.53 Fe Cor Post

1956 W.S. Moore survey Wit-none

1974 Lapham LCRC#90 & survey Found 1 1/2" Bar in Mon Box Wit-(6)N50W 91.55 Cor Fe Post (7)S45W 69.43 T.P. (8)S50E 95.74 P.P.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1 ½" Iron in Monument Box 5 feet West of centerline M-18, opposite centerline road to West, and 5 feet North of 2-track road to East. Iron agrees with 1938 MSHD notes and measurements to K-7 and K-5. It also agrees with Moore (1956) and Lapham (1974) measurement to K-5

See dossier for detailed report.

APPROVED LAND CORNER P.A. 345 of 1990

2

-1

11 -12

14 **1**3

. J.,

23

26

35

25

36

10

15

22

27

Q

16

---

21

28

33

17

20

29

32

Gladwin County

Co. Rep.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6: 1/4 Corner common to Sections 13 & 14. Set 5/8" x 18" rerod in Monument Box with Gladwin County Remonumentation cap marked P.S.#27458.

Witnesses:

S50°E Power Pole, nail & tag, 93.17' (MDOT) N55°E Top Center R/W Mon 80.89' (MDOT) N40°W 14" W. Pine, nail & tag, 96.80' S75°W "X" in West Edge of North Wing Wall Culvert 64.90' East 1/2" x 18" Iron Center 2-track 85.68"

Surveyor's Michigan License No. 27458

Date

ROBISON ROFESSIONAL SURVEYOR No. 27458 POFESSION COMMON !

OF MICHIGA

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. REVISED MAY 14, 1975 REVISED JAN., 1983

REVISED OCT., 1995