LIBER 001 PAGE 90

JAN 1 7 1996 LAND CORNER RECORDATION CERTIF Filing Requirement of Act 74, Mich. P.A.	
For corners in COMMISSION GLADWIN Located In: Corner Code #	STATE OF MICHIGAN GLADWIN COUNTY FILED-REMONUMENTATION
1. Public Land Survey T19N R 2W I-7	26 DEC 95 10:54 A.M.
TR	RONNIE K. HOUSE REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJK L
I, PAUL B. LAPHAM, in a field survey on NOVEMBER, 19 95 do hereby state that und requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and // that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:	2
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration: 1856 LEVI H. CANNON 1987 LAPHAM SURVEY #G-877 SET POST WITSAME AS (3) (4) & (5) ABC WIT(1)W. PINE 12" N53*E 4 (2)BEECH 10" S27*W 33 1988 LAPHAM SURVEY #G-888	VE.
WIT SAME AS (3) (4) & (5) AE	
1991 LAPHAM UNRECORDED L.C 1975 PAUL LAPHAM L.C.R.C. \$108 FOUND 3/8" IRON WIT.—(6)N45% POWER POLE 50.5: WIT.—(3)N45% 44.97' FENCE POST (4)S45% 44.52' TELE. POLE (5)N45% 50.80' POWER POLE (6)N45% No.80' POWER POLE (7)N45% CORNER POST (8)S45% TELE. RISER 44.52' (9)N70% N. TOP CENTER 18	2'
B. Description of corner evidence found and/or method applied in restoring or reestablishing of	corner:
FOUND 3/8" IRON INTERSECTION COUNTY ROADS, EXCAVATED FOUND NO OTHER CORNIN PLACE OF FOUND 3/8" IRON, MATCHED WITNESSES (4), (6), (7) & (8) This Corner established in Gladwin County Remonumentation Program. See dossier for detailed report. C. Description of monument for corner and accessories established to perpetuate locating the I-7: CORNER COMMON TO SECTIONS 14, 15, 22 & 23	PAUL B. LAPHAM PROFESSIONAL SURVEYOR No. 9433
SET 5/8"x36" RE-ROD WITH GLADWIN RE-MON CAP MARKED NO. 9433 WITNESSES: N45"W 50.50' NAIL & TAG IN POWER POLE. N45"E 46.70' NAIL & TAG IN CORNER POST S45"E 44.65' NAIL & TAG IN TELE. RISER & POLE S45"W 50.87' NAIL & TAG IN CORNER POST CO. Date	10/10/04
Signed by Paul 1. 10hh Date_	12-22-91
Surveyor's Michigan License No. 9433	