SURVEY & REMONUMENTATION

OCT 2 3 1998

Surveyor's Michigan License No. ___27458

GLADWIN County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 213

	SECTION	
or corners in	⊕ , .	

STATE OF MICHIGAN Corner Code # Located in: **GLADWIN GLADWIN COUNTY** FILED-CORNER T20N R02E A-6 Public Land Survey 13 OCT 1998 12:44:45 PM R R PONNIE K. HOUSE 1 R REGISTER OF DEEDS 2. Property Controlling R in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims I, __Mark R Robison_____, in a field survey on May_____, 19_98_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the state of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan⁶ Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate 10 11 12 A. Description of original monument and accessories and/or subsequent restoration: A-6: 1837 Louis Mason-Set 1/4 Post Sec 1985 Lapham (survey & dwg)-Fd 1/2" Post Wit-(1)B. Ash 11 S49W 11 links Bar Wit-(7)N30E 8" Cedar 59.0 (2)Cedar 6 N75W 28 links 1967 Hennings Fd 1/2" Iron; Wit-none (8)N80E C.I. 33.00 (9)S45W Tele Riser 39.90 1977 Hennings Fd 1/2" Iron; Wit-none 1994 Lapham (survey & dwg) 1978 Lapham (survey & dwg)-Fd 1/2" Wit-same as (7),(8) & (9) Pipe 1996 DNR--LCRC#372 Fd 1/2" Rerod Wit-(3)S60W T.P. 39.70 Wit-(10)4" W. Pine N52E 48.81 (4)West Dead End Sign (11)18" W. Pine N88E 56.34 (5)N60W 10" Poplar 38.00 (12)6" W. Pine S34E 73.67 (6)\$80E 4" Poplar 43.80 (13)5" W. Birch S66W 49.98 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-6: Found 1/2" rerod inside 3/4" x 20" pipe in centerline of See dossier for detailed report. North-South road. Corner agrees with 1967 survey by Henning. Corner fits witnesses (6), (7) & (11). Accepted 1/2" iron. Removed and Set Gladwin County Remonumentation. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-6: W 1/4 Corner of Section 18, located on township line. Set 5/8" x 36" rerod with Gladwin County Remonumentation Cap marked P.S.#27458. APPROVED LAND CORNER A. 345 of 1990 Witnesses: N30E 10" Cedar, (survey cap & spike) 58.98' **Gladwin County** S80E 8" Poplar, spike, 43.75' N88E 18" W. Pine, spike, 56.35" S45E 8" Poplar, nail & tag, 73.20' MARK R. ROBISON PROFESSIONAL Date SURVEYOR

No.

27458 6