LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Gladwin (County)	Located In Corner Code #	
 Public Land Survey Property Controlling in Section Miscellaneous Property in Section 	T 20N R 2E K7 T R	Register of Deeds Stamp & File Number
4. Lot No: 5. Private Claims:	Recorded Plat:	A B C D E F G H I J K L M
requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board or	field survey on Sept. 20, 2005 do hereby state that under chigan PA of 1970, the corner points mentioned in lines 1 ormance with regulations and rules therefore as required in rvey instructions of the United States Department of the anagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rules of Land Surveyors or by a Decree of a Court of Law; monumented, recovered, found as expressed below:	3 4

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may

K7 – GLO – Set post – J. Mullett – 1846 Y. Pine 16" S35°W 25 L. Beech 10" N14°E 32 L.

CSR – P. 105 – I. Knox – 1908 – Cedar 3' x 3" x 3"
 Pine Stp. 24" S28°E 72 L.

Pine Stp. 24 S28 E 72 L. Pine Stp. 18" N27°E 52 L.

be recorded on this certificate.

- CCC Notes – 1930's – N 240:00 – Set Random post - 1.32 CH N. of center E-W Rd. East 80 CH – Set Random post 0.5 CH E of N-S Line.

- LCRC # 141 and Rec. Sur. L. 1, p. 699 – T. P. O'brien –1976-Fd. 3/8" iron bar; 5" Tri-Maple N43°W 54.35'; 6" Spruce S13°W 31.95'; 6" Maple Clp. - S52°E 52.0'

- LCRC #386 - C. F. Roser - 1995 - Fd. ½" rerod 1' below rd. surface. Fd. 3/8" x 9" rod w/ battered PS Cap ½'± E. of rerod. Drove 1" pipe over ½" rerod and put 3/8" rod inside 1" x 15" pipe. Cor. falls in approx. CTR E-W gravel road. CTR of Trail Rd. N. is 5'± East. 7" W. Pine N35°W 68.0'; 10" W. Pine N40°E 96.9'; 10" Maple (Clp. 4) S50°E 51.8'; 10" Trpl. Maple S20°W 65.4'. Set Cedar post w/ Loc. Tag South 33'.

- LCRC #466 - D. L. Winiecke – 2000 – Fd. 1" pipe 0.5'± below grade per LCRC #386 – Same witnesses as Roser.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K7 – Sec. Corner common to Sec. 13, 14, 23 & 24 – Fd. ½" x 3" long capped rebar at surface of E-W Bit. Rd. − 1'± N. of centerline. Removed ½" x 3" CIR and excavated below iron and found 1" pipe per Roser & Winiecke LCRC's. No conclusive GLO or CSR BT's. Centerline of 2-track N. is 7'± E. 1" pipe accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K7 – Drove stamped 2 ½" Brass Cap on 5/8" x 24" rebar inside found 1" iron pipe. Add Mon. Box. N42°E 97.15' to set N & T in NW side 12" W. Pine (CFR, DLW) N38°W 68.46' to set N & T in SW side 12" W. Pine (CFR, DLW) S16°W 65.78' to set N & T in NW side 12" Maple clp. – 3 (CFR, DLW) S50°E 52.66' to set N & T in NE side 12" Maple clp. – 5 (TPO, CFR, DLW) South 33' Cedar post w/ loc. tag.

CRAIG W.
MCVEAN
PROFESSIONAL SURVEYOR
NO.
39088

Signed by:

Surveyor's Michigan License No.:

39088

Date: 5/9/2007