AUG 2 3 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

UBER 001 PAGE 329

## Filing Requirement of Act 74, Mich. P.A. 1970

Gladwin County Remonumentation

STATE OF MICHIGAN GLADWIN COUNTY FILEU-REMONUMENTATION

10 AUG 2000 11:24:36 AN

BONNIE K. HOUSE REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For Corners in **GLADWIN** Corner Code#: Located In: (County) B-11 T. 20N R. 2W 1. Public Land Survey R. 2, Public Controlling R. in Section 3. Miscellaneous R T. Property in Section Recorded Plat 4. Lot No. 5. Private Claims

1, Mark R. Robison, in a field survey on April 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established mentallished manumented responsement recovered found as expressed below. Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

DEFGHI 10-16 15 18 24 22 23 19 20 21 25 28 27 26 29 30

A. Description of original monument and accessories and/or subsequent restoration: 1981 Lapham--survey

1856 Nicholson Set QR. Sec Post Wit-(1)Elm 8 N48E 25 lks (2)Cedar 14 S54E 10 lks

1991 Lapham--survey Wit-same as (3), (4) & (5)

Wit-same as (3), (4) & (5)

1993 Erickson--LCRC#351 Found 1/2" Rod Wit-(6)N63E 55.55' N&W in Power Pole (7)S28E 83.33' Power Pole (8)S13E 44.81' Face of Stop Sign (9)N38W 44.92' SE Cor Tele Riser Box

1998 Lapham--survey Set 1/2" Rod Wit-same as (6), (7), (8) & (9) (Reset in Mon Box)

1977 Sedgman LCRC#77, survey, working drawing Set 1/2" Bar. at prorated GLO measure Wit-(3)S30°E 83.33' Power Pole (4)N65°E 55.17' Power Pole (5)N40°W 45.39' Tele. Pole

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found ½" x 18" rerod in monument box. Agrees with witnesses (3) Recorded & measured 83.33' & (4) Recorded 55.17', measured 55.55' (pole leaning away from corner--would agree if pole were in vertical position). Agrees with measurements to C-11 by Sedgman (1976) (pole leaning away from corner--would agree it pole were in voltage positions). Accepted found 1/2" rerod as corner of record; replaced with 5/8" x 36" rerod 2637.41' & Lapham (1998) 2637.69'. Accepted found 1/2" rerod as corner of record; replaced with 5/8" x 36" rerod 2637.41' & Lapham (1998) 2637.69'. P/A. 345 of 1990

See dossier for detailed report on corner B-11.

Gladwin County Rep

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Gladwin Remonumentation cap marked P.S. 27458. Accepted as best available evidence to perpetuate position of E OF MICHIGA comer B-11.

Witnesses: N65°E Power Pole, nail & tag, 55.55' (OBT) S30°E Power Pole, nail & tag, 83.33' (OBT) S25°W Power Pole, nail & tag, 70.15 (NBT) N44°W 5" W. Pine, nail & tag, 82.50'

North & East, P.K. nail, 2.0'

Moun 1 Signed by Surveyor's Michigan License No. 27458 Date\_

No. 27458 OFERSION

RORISON

POFESSIONA

Form approved by Michigan State Board of Land Surveyors, Jan.28, 19 REVISED MAY 14, 197 REVISED JAN., 191 REVISED OCT., 191