GLADWIN COUNTY REMONUMENTATION

DEC 1 6	LAN	ND CORNER RECORDATION CERTIFICA ling Requirement of Act 74, Mich. P.A. 197	
For corners in GLADWIN		Corner Code #	STATE OF HICHIGAN
(County)	Located In:	Coffice Code #	GLADWIN COUNTY
1. Public Land Survey	· · · · · · · · · · · · · · · · · · ·	R_1WG7	FILED-REMONDMENTATION
		RR	2 DEC 96 3:34 P.H.
	T	R	BONNIE K. HOUSE
2. Property Controlling in Section		RR	REGISTER OF DEEDS
3. Miscellaneous Property in Sec.	S T	R R	Davistas of Davide Otemps 9 File Number
Troporty in coo.	<del></del>		Register of Deeds Stamp & File Number
4. Lot No, Recor	ded Plat		ABCDEFGHIJKL
5. Private Claims			1 2 6 5 4 3 2 1
		•	3
I MARK ROBISON	. in a field survey (	November 19 96 do hereby state that under	4 7 9 10 11 12
nametromento of D A 74 Michiga	an P∆ of 1970 the c	orner points mentioned in lines 1 and 2 above were in ulred in the current manual of survey instructions of the	5
Linked Cinter Department of the I	Interior Rureau of Lan	id Management or by a decree of a Court of Law and /or	6 18 17 16 15 14 13
that the corner points mentioned	in lines 3.4 and 5 abo	ove were in conformance with the rules of the Michigan rt of Law; established, re-established, monumented,	7
recovered, found as expressed below:			8 19 20 21 22 23 24
	ners, all in the same '	town and range, may be recorded	9
on this certificate.		•	10 30 29 28 27 26 25
			11
			13
	onument and acces	sories and/or subsequent restoration: WIT(3)SE COR TOWNHALL N42W 86.95	POSSIBLY 1 1/2" DEEPSET NAIL
1856 GEO E. ADAIR Intersected old cor at post witNone	r	(4)SE COR WELL N50W 68.65 (5)FENCE COR N45E 47.88	WIT(6)NW 56.8 T.P. (7)NE 39.4 P.P. (8)SW 43.7 COR F. POST
1908 KNOX SURVEY		1973 PAUL LAPHAM SURVEY & WORKING DRAWING	(9)SE 41.5 COR F. POST
SET GAS PIPE WIT(1)SE COR TOWNHALL NW 1			1987 EDMANDS ENG-ROAD PLANS WIT{10}NW 86.9 TO SW COR BLDG.
(2)NW FENCE POST S45 1/2E 6	.2	1977 PAUL LAPHAM-PLAT FAIRFIELD REALM	(11)NE 63.0 TO C/L M.H.
1969 PAUL LAPHAM-SECTION SU FOUND GAS PIPE	IBD.	1980+/- EDMANDS ENG-REACTION	(12)SW 126.55 TO NE COR BLDG.
	idence found and/c	r method applied in restoring or reestablishing cor	ner:
FOUND P.K. NAIL IN PATCH OVE REALM. FOUND WITNESSES (11) SEE DOSSIER FOR DETAILED RE	); R&M 63.0. SET GLAD	SURFACE IN C/L OF ASPHALT ROAD & T-ROAD TO EAST; A DWIN RE-MON FROM FOUND IRON & WITNESS (11) AND PLATE APPROVING A CITY	GREES WITH SOUTH LINE OF PLAT OF FAIRFIELD AT OF FAIRFIELD REALM; MEAS, TO G-8, 2644.06.  ED LAND CORNER  WAS OF 1878  WAS CORNEY
,		Ço. Rep.	Cercles
		Date 11/6/91	The state of the s
C. Description of monumen	t for corner and acc	cessories established to perpetuate locating the po	45° Co
G-7: CORNER COMMON TO SEC SET 5/8" X 38" REROD WITH GLA	TIONS 15, 16, 21 & 22 ADWIN RE-MON CAP M	ARKED P.S.#27458 IN MONUMENT BOX.	MARK R.  MARK R.  ROBISON  N E PROFESSIONAL
WITNESSES: N45E M.H. TOP CENTER 83.05' N45W TWP, HALL SE COR BRICK S85W BLDG (NE COR FOUNDATI	K 133.05' NOR	N BLDG (SE COR FOUNDATION) 156.73' (TH, P.K NAIL, 2.0' T, P.K. NAIL, 2.0'	SURVEYOR No. 27458
Signed by Man	n (2. Com	Date	11-29-96

27458

Surveyor's Michigan License No.\_\_\_