## COLLINCOINE

## LAND CORNER RECORDATION CERTIFICATE

Register'	8 Office	
Register' Gogebic	County	S

Received for record the
A. D. 19 95 at 1:15 o'clock  P. m., and recorded in
Liber 5 of CORNERS
Romana Collins Deputy

GOMINISSION For corners in		Filing Requi	Filing Requirement of Act 74, Mich. P.A. 1970  Received for record the 23 RD day of NYARCH	
	Gogebic	Located in:	Corner Code <i>++</i>	A. D. 19 95 at 1:15 o'clock
1.	Public Land Survey	T <u>45N</u> R <u>41W</u> T R T R	<u>1-3</u>	Liber 5 of Corners on page 220 Ramona Calling, Deputer
2. 3.	Property Controlling in Section Miscellaneous	S T R S T R S T R		Register of Deeds
υ.	Property in Sec.	S T R		Register of Deeds Stamp & File Number
		ecorded Plat		2 6 5 4 3 2 3
do in cu Ma ab Co	hereby certify that under requires 1 and 2 above were in trent manual of survey instru- anagement or by a decree of a love were in conformance with	uirements of P.A. 74, Michigan P.A. conformance with regulations a ctions of the United States Depa Court of Law and/or that the corrother rules of the Michigan Board	ober 5 19 93 A of 1970, the corner points mention and rules therefore as required in the interior, Bureau of Lander points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of Land Surveyors or by a found	ed he of the order
NOTE. Not more than 4 corners, an in the same town and range, may be recorded				11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Algernon Merryweather, U.S. Deputy Surveyor on June 11. 1852 Original Corner: Wood Post

Original Bearing Trees:

s 53°W Sugar N 65°E 14" E1m

(7.92 feet) 12 links 27 links (17.82 feet)

Richard Drahn, RLS #21564 monumented this corner in July, 1981 and set a 2" X 30" long aluminum pipe monument.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence remains of the original corner or bearing trees.

Corner position set by Richard Drahn RLS (U.S.F.S.) found to be in error and not consistent with measurements in surrounding sections. Corner appears to be approximately 60 feet short between the SW corner of Section 2 and the S 1/4 corner of Section 2. I could not accept the monument as set. No other evidence available in the area for restoring the corner position.

I restored the corner position using Double Proportionate measurement methods between the SW corner of Section 3 and the S 1/4 corner of Section 2 and between the NE corner of Section 3 and the E 1/4 corner of Section 10.

Richard Drahn RLS agreed that I could move his monument to the Double Proportioned position which better represents the true location of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I reset 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T45N, R41W, S-3, S-2, S-10, S-11, 1981, RLS- 21564 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Sugar Maple 7" N 84°E 8.76 feet

S 21°W 7" Red Maple N 13°W N 75°W 7" 15.75 feet Sugar Maple Steel Sign Post EER GROUP APPROVED

35.74 feet

1.06 feet

OF MICHICAN **PISONI** LAND SURVEYOR No. 27457

Surveyor's Michigan License No. .

Sugar Maple

REVISED MAY 14, 1975

REVISED JAN., 1983