BUHVEY & REMONUMENTATION

NOV 1 2 1997

For corners in

-. Private Claims

COMMISSION

Register's Office Cogebic : punty

AND CORNER RECORDATION CERTIFICATE	
iling Requirement of Act 74, Mich. P.A. 1970	Received for record the
	9 TH day of October

Gogebic Located In: Corner Code ## A. D. 19 97 at 10:50 o'clock 🚣 ... m., and recorded in T46N R 46W . Public Land Survey Liber 6 OL COLNERS _ R _ page .. 220

Kamona Collins Deputy Register of Door

Register of Deeds Stamp & File Number

T <u>45N</u> R <u>46W</u> Property Controlling in Section S Miscellaneous T ... __ R . Property in Sec.

Section Corner 5, 6, 31 & 32; T.45-46 N., R.46 W. Section Corner 5, 6, 31 & 32; T.45-46 N., R.46 W.

_ , Recorded Plat _

__Drahnin a field survey on _October 2 To hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ÷bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Fourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

5 7 10 11 12

BOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

... Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on August 31, 1847. Original B.T.s --- Cedar 12" N.70 E. 34 links (22.44') --- Sugar 16" N.19 W. 8 links (5.28') --- Hemlock 18" S.60 W. 64 links (42.24') --- Y. Birch 22" S.72 E. 12 links (7.92') ---

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the last three bearing trees. The Sugar is now a large windthrown stump hole and the Hemlock and Y. Birch are now badly decayed stumps. The 27.10 chain distance west to the recovered C.C. of sec"s 31 & 6 and the 7.93 chain distance south to the recovered C.C. of sec's 5 & 6 are in accordance with the field notes of the original Government survey. No evidence remains from the original Cedar B.T.

Research form on file with Gogebic County records.

PEER GROUP APPROVED

Exerciption of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2" X 30" aluminum pipe with a $3\frac{1}{4}$ " aluminum cap stamped to indicate the corner position and the following new B.T.s.

7" Sugar Maple S.12 E. 15.08 11" N. Red Oak S.70 W. 26.24 7 11 Sugar Maple N.16 E. 14.28 6 ' Steel sign rail N.13 W. 2.31

OF MICH RICHARD L. DRAHN LAND SURVEYOR No. 21564 LAND

-igned by .

____ Date <u>October 6. 1997</u>

urveyor's Michigan License No. __21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983