## REMONUMENTATION

. NOV 1 2 1997

COMMISSION LAND CORNER RECORDATION CERTIFICATION Filing Requirement of Act 74, Mich. P.A. 19	Pasakia Pasakal
CONNIVIOのよう Filing Requirement of Act 74, Mich. P.A. 19 For corners in	Received for record the
Gogebic Located In: Corner Code #	974 day of October
(County)	A. D. 19 97 at 11:00 o'clock
1. Public Land Survey  Section 3 T <sup>46N</sup> R 42W H-3	A m., and recorded in
T R	Liber 6 OF CORNERS
<u>TR</u>	m page 239
2. Property Controlling S T R	Ramona Collins, Deput
in Section S TR	Register of Doods
3. Miscellaneous ST_R	
Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	1
The one quarter section corner common to sections 3 and 10, T46N, R42W.	2 6 5 4 3 2 1 1
I. I. D. Camiles in a fold current on Take 1977, de bereits that under	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, John R. Garske, in a field survey on July 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	5
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 -18 -17 -16 -15 -14 -13 -
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	8 19 20 21 22 23 24
	9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
on this certificate.	
	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
•	
Original Corner set by A. Merryweather, D.S. in 1851. Original Bearing trees:	
A Lynn 14"-N36W 15 links	·
A Cedar 12"-S41E 17 links	
B. Description of corner evidence found and/or method applied in restoring or reestablishing cor	ner:
I found 1" dia. axle rod approximately 210' east of South East Shore Road. A blu	e line rune north couth and eact
from this corner position which was pointed out to me by Don Holmes, Champion	
County Road Commission plans dated 1933 show this corner position monument	
used and accepted for over 50 years as being in the correct location with no dispute corner.	es and I am accepting it as the 1/4
Wind.	
(Research on file)	
C. Description of monument for corner and accessories established to perpetuate locating the po	sition of the corner:
OFF.	GROUP APPROVED
$\mathcal{P}(\mathcal{F}_{\mathcal{A}})$	P1). 12 10/8/97
(adamo	THIE DEPRESENTATIVE
I replaced the axle rod and set a 30" long x 2 1/2" dia. aluim, pipe monument with	a 3 1/4" stamped alum. cap from
which I established the following: 7" Hard Maple North 15.27 feet	OF MICHIGA
20" Hard Maple S58°E 7.05 feet	STATIONN P. 177
20" Hard Maple S62°W 24.99 feet 5" Hard Maple N62°W 14.23 feet	JOHN R. CARSKE
(104 a) Ci mi mail 01697/ 1.20 fact 0	6/7/Q07 **
Signed by	A 1 SURVEYOR 1 * 1
Surveyor's Michigan License No.	No. 28410
V 28410	
FORM APPROVED BY MICHK	REVISED MAY 14,19
	REVISED JAN., 19