## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office See Segebic County See.  Received for record the 10.74 day of Junia  D. 1999 at 10:05 o'clock  A m., and recorded in the 157  Ramona Collina Digital Register of Deads
Register of Deeds Stamp & File Number
A B C D E F G H I J K L M  5 - 5 - 4 - 3 - 2 - 1 - 3 -

For corners in Corner Code # Located In: Gonebic (County) <u>1-8</u> T46N R43W 1. Public Land Survey 2. Property Controlling in Section R 3. Miscellaneous S Property in Sec. Quarter Corner 22 & 23; T.46 N., R.43 W.

, 19 99 do hereby state , in a field survey on May 14 that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt on 9/5/1851. Original bearing trees: 27 links (17.82') S.48° W.

28.63

N.46° E. 10" Cedar

, Recorded Plat

4, Lot No. 5. Private Claims

21 links (13.86')

Corner restored by Richard L. Drahn, RLS 21564 on 10/22/84 from the remains of the original Cedar B.T. and from natural feature ties north and a line tree south. He set a 3/4" X 4' aluminum rod monument with a 3 1/4" stamped aluminum cap and the following B.T.s: 23.29'

N.43° W. 9" Cedar N.43° E 5" Cedar S.18° W.

4.65 Cedar 2.37 N.48° W. 6' Steel sign rail

Corner recorded in Gogebic County Liber 2, Page 649 on 12/10/84.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: I recovered the monument as described and the bearing trees as follows:

23.34" N.42° W. Cedar N.43° E. 28.561 6" Cedar S.21° W. 4.65 9" Cedar 2.38 N.49° W.

6 Steel sign rail Portions of the original Cedar stump still remain.

Corner research on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

New bearing object referenced:

Cedar

S.75°E.

25.70"

1:

Date May 23, 1999

21564 Surveyor's Michigan License No.

USFS P-17

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983 REVISED OCT., 1997

Ť.

RICHARD

L. DRAHN

LAND

SURVEYOR No.

LAND