MAR 02 2000

SECTION For corners

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register	s (Mire)	
Gogebic	oupty)

	Received	for record the
	2day	Ol MAY
. D.	19 99 1	10:30 o'clock
	A	and recorded in
Ber	7	d CORNERS
	de 135	
Zα,	mona C	olling, Deput
1	Į.	erister of Deeds

Corner Code ## Located In: Gogebic т<u>46N</u> н <u>43</u>W Public Land Survey \mathbb{R} R T46N R 42W _ R _ Τ_ **Property Controlling** S R in Section S. S Miscellaneous

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5.	Private Claims


R

Section Corner 6, 7, 1 & 12; T.46 N., R.42-43 W.

Т

April 9, I, Richard L. Drahn in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt on August 6, 1847. Original B.T.s --- 16" Y. Birch N.78 W. 25 links (16.50') --- 10" Y. Birch N.38 E. 30 links (19.80') --- 10" Y. Birch S.60 E. 73 links (48.18') ---

Corner restored by Richard L. Drahn, RLS 21564 on 7/20/78 from the remains of the three original B.T.s. He set a 2" X 5' iron pipe with a 3" stamped brass cap and the following new bearing trees:

30.81 N.10 W. 8 11 Red Maple 6" Red Maple N.85 E. 12.5' s.30 W. 35.21 15" Hemlock

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Steel sign rail South

Corner recorded in Gogebic County Liber 1, Page 436 on 1/17/79.

Corner research on file with Gogebic County records.

Recovered the monument as described and the bearing trees as follows:

N.13 W. 30.761 11" Red Maple 12.47' 8" N.83 E. Red Maple 35.37' 19" S.30 W. (new nail) Hemlock 3.23' Steel sign rail South

Depressions are still evident from the first two original B.T.s and a decayed Yellow Birch stump remains from the third.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing tree referenced:

8" Red Maple S.43 E.

38.381



Date <u>April 11, 1999</u>

21564 Surveyor's Michigan License No. 🔔

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

USFS E-25