LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

GOGEBIC COUNTY	Register's Office ss.
FOR CORNERS OF -: LOCATED IN -: CORNER	CODE NUMBER Received for record the
1. PUBLIC LAND SURVEY T. 46 N., R. 44 W. A-	10 <u>5 day of January</u> A. D. 19.74 at 10:05 o'clock
2. PROPERTY CONTROLL- N. E. ING IN SECTION T. S., R. W.	A in., and recorded in
3. MISCELLANEOUS PROPERTY IN SECTION, T S., R W.	Liber 4 of Gonnass on page 350
4. LOT NO, RECORDED PLAT	Annroyed Betty Sagre Deputy
97 1/ V P (1.1 1/ 1.1 1.1	
Quarter corner 30 & 25, T46N, R44-45W.	BEGISTER OF DEEDS STAMP AND FILING NUMBER
I, Richard L. Drahn do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on June 10 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:	
A. Description of original monument and accessories and/or subseque	ent restoration:
Original corner established by Austin Burt, U.S. I Original bearing trees: Hemlock 20" S.86°E. 20 link Hemlock 14" N.26°W. 30 link	(s (13.20 feet)
17.09 chains south Y.Birch 18" line tree 15.11 chains north Y.Birch 20" line tree	(10100 1000)
No record of subsequent corner restoration found.	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Restored corner position at record bearing and distance from the remains of the two original hemlock bearing trees. Both B.T. stumps are decayed to well below ground level. The line tree 17.09 chains south of the corner is now a decayed 24-28" yellow birch stump. The line tree 15.11 north of the corner is now a 36" live yellow birch. Corner position lays within 1 foot of a mathematical analysis of the range line between ranges 44 and 45 west.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: At the corner position I set a standard 2 1/2" diameter by 30" long split base aluminum monument with a 3" cast aluminum cap, stamped to read: T46N, R44-45-W; 1/4; S-30, S-25; 1993; R.L.S. 21564. From which I have established the following new blazed and scribed bearing trees: 10" Red Maple N.44°E. 13.98 feet 14" Hemlock S.23°E. 7.48 feet 13" Hemlock S.74°W. 11.01 feet 6' Steel rail S.50°W. 2.02 feet	
SURVEYOR'S MICHIGAN REGISTRATION NO.	* RICHARD
FOR STATE AND UNITED STATES AGENCIES:	21564
SIGNED BYCHIEF OF SURVEY PARTY	DATE
APPROVED AND SIGNED BY RICHIGAN REGISTERED LAND SURVEYOR	DATE December 20, 1993
FED T-1	(SEAL)
SURVEYOR'S MICHIGAN REGISTRATION NO. 21564 FORM NO. MLM735 DOUBLEDAY 9805. & CO., KALAMAZOO, MICH. FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS	