SURVEY & REMONUMENTATION

JUN 2 9 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Register's Office Gogebic County

For corners in	Filing Require	ment of Act 74, Mich. P.A	A. 1970 Received for recent the	v
Gogebic	Located In:	Corner Code ##	A. D. 1995 at 10:56 o'clock	,
1. Public Land Survey Sec	tion 35 T <u>47N R 42W</u> T R T R T R	K-13	An., and recorded in Liber 5 of CORNER on page 183	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds	
5. Private Claims	in a field survey on Octourements of P.A. 74, Michigan P.A. o conformance with regulations and citions of the United States Department of Law and/or that the corner of the rules of the Michigan Board of restablished, monumented, re-more the rules of the same town and others, all in the same town and	ther 14 , 19 94 f 1970, the corner points mention rules therefore as required in nent of the Interior, Bureau of Lapoints mentioned in lines 3, 4 ar Land Surveyors or by a Decree onumented, recovered, found	2 6 5 4 3 2 3 4 7 8 9 10 11 5 14 6 15 14 6 16 15 14 6 16 15 14 6 16 16 16 16 16 16 16 16 16 16 16 16 1	12-13-13-24-14-25-14-14-14-14-14-14-14-14-14-14-14-14-14-
on this certificate.			12 31 32 33 34 35	36-

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by William A. Burt, Deputy Surveyor, in 1847. Set a hemlock post from which a: 12" Sugar - N54°E - 17 links 18" sugar maple - S28°W - 13 links 19" sugar - N57°W - 36 links 10" elm - S50°E - 33 links

1961 - Kimberly Clark Surveyor, Neil Sperhake, RLS 7876, set a 4" diameter aluminum cap on a 1 1/4" diameter pipe at the corner position (see reference below).

1969 - Corner recorded by Don Lappala, RLS 12585, April 17, 1969, in USFS Liber pg. A-21, LI, pg 85 of Register of Deeds (see reference below).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the Sperhake (Kimberly-Clark Corporation) monument in good condition with his bearing trees, a 14" sugar maple - N26°W - 56.1 feet; 11" hemlock - N52°E - 44.2 feet; 6" elm - S08°E - 40.9 feet; 10" hemlock - S56°W - 44.9 feet (all destroyed). Lappala's bearing trees: 5" yellow birch at N26°E - 21.0 feet is in good condition but the 3" elm at S75°W - 16.0 feet is destroyed. I updated the corner to county specs as noted below.

County record research on file with Register of Deeds.

PEER GROUP

Approved

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 4" diameter stamped aluminum cap on a 1 1/4" diameter pipe from which I established the

following bearing trees and reference objects: 5" ash - S22°E - 8.12 feet

4" maple - N81°E - 13.20 feet 9" Y. birch - N30°E - 21.13 feet (existing)

Steel sign post - Due West - 1.50 feet

28410 Surveyor's Michigan License No.

Signed by

No. 2841C CAND

JOHN R.

GARSKE LAND SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 REVISED MAY 14, 1975

Fed. No. Z-21