NOV 1 2 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Register'	s Office	
Kegister' Gogebic	County	} \$ <b>\$</b> .

1. Public Land Survey  T 47N R 44W	Received for record the
1. Public Land Survey	19.97 at 11:00 o'clock
2 Property Controlling S T R	m., and recorded in  6 of Corners  182
in Section S T R	nona Collins Deputy Register of Deeds
3. Miscellaneous         ST R	Deeds Stamp & File Number
4. Lot No, Recorded Plat	C D E F G H I J K L
I, Richard L. Drahn in a field survey on August 8, 19 97  do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, att in the same town and range, may be recorded	17 16 15 14 13 -20 21 22 23 24

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1848. Original B.T.s --- Hemlock 14" N.45 E. 27 links (17.82') --- Hemlock 14" S.60 W. 18 links (11.88') ---

Corner restored on 8/3/83 by R. Drahn (21564) from the decayed remains of the two original B.T.s. He set a 2" X 30" aluminum pipe with a  $3\frac{1}{4}$ " stamped alum. cap and the following new B.T.s: --- 6" (7") Cedar N.04 W. (N.06 W.) 16.86' (16.83') --- 11" (13") Yellow Birch S.32 E. (S.32 E.) 44.66' (44.64') --- 18" (20") Hemlock S.42 W. (S.45 W.) 45.69' (45.70') --- 6' steel sign rail N.11 W. (N.11 W.) 2.37' (2.37') ---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Corner recorded in Gogebic County in Liber 2, Page 553 on 1/26/84.

Recovered the corner as described and the bearing objects as indicated in parentheses above. A stump hole remains from the original NE B.T. and a / badly decayed Hemlock stump with portions of the B.T. blaze remains from i the SW B.T.

Research form on file with Gogebic County records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the above described monument I established the following new B.T.:

Cedar

on this certificate.

N.73 W.

5.88

of Micay RICHARD L. DRAHN LAND SURVEYOR No. 21564 CHAL

Date August 8, 1997

Surveyor's Michigan License No. 21564

FDBM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983