

SEP 29 1994

on this certificate.

Carolin Williams Carolina State

Fre & some	Date Contain Incompanion Chilling Inchie				angenic cannity }							
For corners in	Filing Requirement of Act 74, Mich. P.A. 1970			Received for record the								
Gogebic	Located In:	Corner Code ≄#	-		6-	da;	of.	5 15/	751	111		
(County)				A. D. 19 4# at 3:20 o'clock								
1. Public Land Survey	T <u>47N</u> R <u>45W</u> <u>E-5</u> T <u>R</u>		Pm., and recorded in liber 5 of Corners									
Property Controlling in Section	T R T R S T R S T R					76 o Cc R						
Miscellaneous Property in Sec.	S T R S T R		Registe	egister of Deeds Stamp & File Number								
	ecorded Plat			4 B	c o	E	F G	H I	<u>, 1</u>	K I	<u>_</u>	
Section corner common to Sections 8, 9, 16 & 17			3	6 	 5 -		-	-3-	2	士	_	
, John R. Garske	in a field survey on	Cant 6 10 04	4	_		+		-10	 -	+	12~	
John R. Garske , in a field survey on Sept. 6 19 94 . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				- 18-	17		6-	-15	-14		13-	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				19-	20	2	1	22			24	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				-30-		2		-27-	-	\pm	25-	
	rmare all in the come town one	d range may be recorded	10				"	ïT	ا		Ĩ	

- Description of original monument and accessories and/or subsequent restoration:
 - Survey by William Burt in 1848, set alder post from which a 10" B. ash bears S60°E, 22 links.
 - On May 22, 1979, E. Muller, RLS 15408 and J. Goss, RLS 23509, found a 1" iron rod in concrete using corner ties provided by the Michigan Department of State Highways and the City of Wakefield Engineer's Ofice. Accessories: P. pole - N43°W, 77.64 fee t; N.W. cor. of Bld. found - N43°E, 40.82 feet; S.W. cor. of Bld. found - S30°E, 59.92 feet; P. pole - S15°W, 41.49 feet, recorded in Liber 1 of land corners, page 488.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 1" iron rod in concrete approximately 20" below the groundmarking the corner position which checks with Muller/Goss certificate as noted above. I updated the corner monument and accessories as noted below to bring them up to state and county specifications.

Record research on file with County Register of Deeds Office.

Approved PFFR GROUP Richard D. 2 9/14/94

Register's Office

Coachin d'anne

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A 19" long x 2 1/2" diameter aluminum pipe with a 3 1/4" aluminum cap stamped to indicate corner position was set on top of found 1" iron rod. I established the following reference objects: N.W. cor. of Bld. foundation - N51°E, 40.82 feet; S.W. cor. of Bld. foundation - S31°E, 59.92 feet; pole - N35°W, 28.22 feet; P. pole - S09°W, 41.49 feet.

Signed by

Surveyor's Michigan License No.

28410

No. 28410

JOHN R GARSKE LAND SURVEYOR

REVISED MAY 14, 1975 REVISED JAN., 1983

FED No. J-9