Company of the second	LAND CODE		ON CERTIFICATI	Register's Office	
Filina Require	ment of Act 74, Mich. F		ON OLIVIII IOA II	E Gogebic County∫ —	
For corners in	,		1	Received for record t	Ìm
Gogebic	Located In:	Corner Code	#	day of JUNE	
(County)				A. D. 19.00 at 10:22 o'clo	
1. Public Land Survey	T <u>47N_R_45W_</u>	<u>K-6</u>		m., and recorded	
111 42110 24110 34111	T R			Liber 7 of CORNE	s es
	TR	SURVEY		page 364)
2. Property Controlling S	TR S T R ⊋	EMONUMEN	TATION	(suy tuppe, a	ep
in Section		F-IAI		Rugister of Dec	400
3. Miscellaneous	5 TR	JAN 052	001-	Register of Deeds Stamp & Fil- Number	0
Property in Sec.	S R	SECTION	L		
4. Lot No, Recor	ded Plat				
5. Private Claims				A B C D E F G H I	К г
Quarter Corner common to Sections 13 & 14.				2 5 4. 3 2	
				3	
				4 - 7 - 8 - 9 - 1.0 - 1.1	1
I, John R. Garske	, in a field survey on	April 5 , 2000	do hereby state	5	-
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current				6 18 17 16 15 14	- -
manual of survey instructions of Management or by a decree of a C	the United States Departm	ent of the Interior, corner points mentic	Bureau of Land oned in lines 3, 4	7	
and 5 above were in conformance	with the rules of the Michig	an Board of Land S	urveyors or by a	9 - 19 - 20 - 21 - 22 - 23 -	
Decree of a Court of Law; establis below:	hed, re-established, monume	ented, recovered, for	ind as expressed	10 20 20 20 20 20 20 20 20 20 20 20 20 20	
		í.		14 30 29 28 27 26	
	ers, all in the same town a	and range, may be	recorded	12 31 32 33 34 35	
on this certificate.				13	
			4 4	.	
A. Description of original mon Corner established by V	ument and accessories ar Villiam Burt, in 1848.	nd/or subsequent r	estoration:		
Original Corner: Cherry	post				
Original Bearing Trees:	10" Yellow E 12" Yellow E		12 Links 27 Links		
	12 16110W L	31011 3 13 14	Z7 LIINS		
B. Description of corner evider	and found and/or mathed	analied in restoring	or recetablishing	ed corner.	
No original evidence found.	ice found and/or method a	applied in restoring	or recotablishing (Jonner.	
_			4- 4b- Caudh 18	Witness Dand also was North and E	agt fr
the quarter corner locat	ine running to the West ion. I monumented the $\%$	and another runnir corner at the inte	ng to the South. Wersection of the and	Viitanen Road also runs North and Educion Road.	451 111
Record Research on File	3.		_ BF	er Grunnafykure	
•			ه · را م	DO O	
			rechord	OURTY BEEN STEAM STATE	
C. Description of monument for	or corner and accessories	established to perp	_		
l set a 5/8" × 30" sectio	on of rebar with a 31¼ ″alı	minum cap at the	intersection of the	fencelines and road, from which !	
established the following	g witnesses:			The state of the s	
8" Maple	N 83° W	30.55 Feet		OF MICHAEL	

 8" Maple
 N 83° W
 30.55 Feet

 Power Pole
 S 39° E
 46.95 Feet


 14" Spruce
 S 04° W
 34.77 Feet

 Reference Monument
 S 44° W
 35.99 Feet

(with steel sign post)

Signed by Carrie

Surveyor's Michigan License No. 28410



FORM APPROVED BY MICHIGAN STATE BOARL PROFESSIONAL SURVEYORS, JAN. 28, 1 REVISED JAN., 1 REVISED OCT., 1